



**Albatross Equipment Earthworks**  
10998 WY-789 Riverton, WY 82501  
[www.albatrossequipment.com](http://www.albatrossequipment.com)

## **Inspection Checklist for 2018 Bobcat T770**



### **Inspection Checklist**

#### **1. Engine and Performance**

Engine Operation: Smooth and responsive, no unusual noises or vibrations.

Engine Oil: Level within specification, clean with no contaminants.

Cooling System: No leaks or blockages; radiator and fan in good condition.

Air Filter: Checked and cleaned; no obstructions.

#### **2. Hydraulic System**

Hydraulic Fluid Levels: Within recommended range, no leaks detected.

Hydraulic Hoses and Lines: No visible wear, cracks, or leaks.

Auxiliary Hydraulics: Fully operational; flow and pressure meet specifications.

#### **3. Loader Arms and Mechanisms**

Loader Boom: Inspected for structural integrity; no cracks, bends, or excessive wear.

Pins and Bushings: Secure and properly lubricated, with minimal play.

Quick Attach Mechanism: Functions correctly, no damage or deformation.

#### **4. Cab and Operator Controls**

Cab Interior: Clean, with all glass intact and undamaged.

Operator Controls: Responsive and free of defects; joystick controls calibrated.

Heating and Air Conditioning: Fully functional; provides consistent performance.

Seat and Restraints: No tears or damage; seat adjustments operational.

## **5. Undercarriage and Tracks**

Rubber Tracks: 85% tread remaining, wear is even and consistent.

Drive Motors: Functioning as intended; no abnormal noise or leakage.

Track Tension: Correctly adjusted to manufacturer specifications.

## **6. Electrical System**

Battery: Tested; holds charge and terminals are clean and secure.

Lights: All operational, including work lights and safety signals.

Instrument Panel: Displays are functional; no error codes present.

## **7. Attachments**

Bucket Condition: 92" GP bucket in good shape; no cracks, dents, or excessive wear.

Auxiliary Hydraulic Connections: Secure, with no leaks or malfunctions.

## **8. General Condition**

Paint and Body Panels: Minor cosmetic wear; no major dents or damage.

Chassis: Solid frame with no structural issues.

Fluids and Filters: Recently serviced; all fluids topped up and filters replaced as necessary.

## **Inspection Summary**

The **2018 Bobcat T770** is in **GOOD CONDITION** with **low hours** relative to its age. This machine demonstrates reliable performance across all key systems. The hydraulic system is leak-free, and the tracks have substantial life remaining (85%). The cab is in excellent shape, and all controls, heat, and A/C function as expected. With its powerful 92 HP engine and additional features like a quick attach mechanism, this unit is well-prepared for immediate use in demanding applications.

Overall Condition: 90%