



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2019 Kubota U35-4



Hydraulic System

- Hydraulic Fluid Levels: Checked and within recommended range. No leaks detected at hoses or fittings.
- Hoses and Fittings: All hoses are in good condition with no visible cracks, abrasions, or wear. Fittings are secure.
- Hydraulic Thumb: Fully operational. No binding or hydraulic leaks observed during function test.
- Hydraulic Cylinders: Inspected for dents or scoring; no abnormalities found. All seals intact with no leaks.

Boom, Arm, and Bucket

- Boom and Arm: Structurally sound with no visible cracks, bends, or weld repairs. Minor wear consistent with hours of use.
- Bucket: 18" bucket shows minimal wear on teeth, and cutting edge is intact. Fully operational with no damage to bucket sides.
- Pins and Bushings: All pins and bushings are tight with no excessive play. Grease points serviced.

Undercarriage

- Tracks: New 12" rubber tracks installed. Tread is in excellent condition with 100% life remaining.
- Sprockets and Rollers: Inspected and in good condition. No unusual wear or damage observed.
- Track Tension: Verified and within manufacturer specifications.

Engine

- Oil Levels: Checked and within normal range. Oil appears clean with no contamination.
- Air Filter: Clean and in good condition. No replacement needed.
- Exhaust: No visible smoke or unusual noise during operation. Muffler is secure and free from damage.
- Cooling System: Radiator and coolant levels inspected; no leaks or blockages found.

Swing Drive and Swing Motor

- Swing Motor: Operates smoothly with no unusual noises or vibrations.
- Swing Bearing: Inspected for wear; no abnormal movement or play detected.
- Lubrication: Grease points serviced and functioning properly.

Cab and Controls

- Interior Condition: Cab is clean with minimal wear. No tears or damage to the seat or upholstery.
- HVAC System: Heat and A/C tested and fully functional.
- Visibility: All glass panels intact with no cracks or major scratches.
- Controls and Gauges: Tested and functioning correctly. No error codes present on the display.

Blade and Attachments

- 67" Float Angle Blade: Blade is in good condition with no bends or cracks. Hydraulic functions tested and operational.
- Auxiliary Hydraulics: Extra auxiliary remote tested; all connections secure and functioning.

Electrical System

- Battery: Tested and holding charge. Connections clean and secure.
- Lights: All work lights and indicators tested and operational.

Paint and Exterior

- Paint Condition: A few minor scratches observed, no rust or significant damage.
- Decals: Intact and legible.