

Albatross Equipment Earthworks

10998 WY-789 Riverton, WY 82501 www.albatrosequipment.com

Inspection Checklist for 2017 NEW HOLLAND C232

General Information:

Model: 2017 New Holland C232

• **Hours**: 1.202

• **Engine**: 74 HP Diesel

• **Hydraulics**: Standard Flow

• **Controls**: Foot Controls

• Quick Attach: Power Quick Attach

• **Tracks**: Very Good Condition

• Backup Camera: Present and Functional

Operating Capacity: 3,200 lbsDEF: Not Equipped (No DEF)



Engine & Performance:

- **Engine Inspection**: Engine operates smoothly with no unusual noises or vibrations. Fuel system functioning as expected.
- Coolant Levels: Within the recommended range. No signs of leaks.
- Air Filter: Clean and free of debris. No visible damage or excessive wear.
- Exhaust System: No leaks or unusual buildup. Exhaust components intact.

Hydraulic System:

- **Hydraulic Fluid**: Fluid levels are within the recommended range. No visible leaks detected.
- **Hydraulic Hoses**: Inspected for wear and leaks. No signs of damage or leakage.
- **Hydraulic Cylinders**: Fully operational. No signs of leakage or damage.
- **Loader Arms**: No visible cracks, bending, or deformation.

Tracks & Tires:

- Tracks: In very good condition with excellent tread. No signs of wear or damage.
- **Tire Pressure**: (If applicable). Tire pressure within manufacturer specifications.
- **Track Tension**: Properly adjusted with no slippage or excessive wear.

Loader & Boom:

- **Loader Arms**: No excessive wear or damage. Smooth operation with no unusual movement or noises.
- **Boom**: Inspected for cracks or structural integrity. No issues found.
- **Lift Capacity**: Loader operates within rated capacity. No issues with lifting performance.

Operator Controls & Cab:

- **Controls**: Foot controls are fully responsive with no issues or resistance.
- **Backup Camera**: Fully operational with clear image quality.
- **Operator Safety**: OROPS structure is intact, and all safety features function properly.

Electrical System:

- **Battery**: Fully charged with no signs of corrosion. Connections are secure.
- **Lights & Signals**: All exterior lights and signals function correctly, including hazard lights and backup lights.
- **Fuses & Wiring**: All fuses in good condition with no visible damage to wiring.

Other Systems & Features:

- **Quick Attach**: Power quick attach functions correctly with no binding or excessive play.
- **Fuel System**: Fuel lines are intact with no leaks. Fuel filter is clean and replaced regularly.
- Exterior Condition: The machine has a well-maintained exterior with no visible damage or excessive wear on the body.

Condition Summary:

The **2017 New Holland C232** is in **very good condition** with minimal wear. All critical systems, including hydraulics, engine, and tracks, are functioning properly. No major repairs are needed at this time. The machine has been well-maintained, with only minor wear consistent with its usage.