



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2019 DEERE 317G

Equipment Details

- Model: 2019 DEERE 317G
- Hours: 978
- Condition: Good



Exterior Condition and Frame

- - Frame: Inspected for cracks, welds, or structural damage – No issues found.
- - Paint and Panels: Checked for scratches, rust, and dents – Minor wear consistent with age and use.
- - Loader Arms: No signs of bending, cracks, or excessive wear – Pass.
- - Canopy: Inspected for integrity and secure mounting – Good condition.

Hydraulic System

- - Hydraulic Hoses: Checked for leaks, cracks, and wear – No leaks detected; hoses in good condition.
- - Hydraulic Cylinders: Inspected for smooth operation and seals – Seals intact, operation normal.
- - Auxiliary Hydraulics: Verified functionality – Fully operational.

Engine and Powertrain

- - Engine: Inspected for unusual noises, smoke, and vibrations – Starts smoothly; no irregularities.
- - Oil Levels: Checked engine oil levels and condition – Within recommended range.
- - Cooling System: Radiator and coolant levels inspected – No leaks; coolant levels adequate.
- - Air Filter: Inspected for dirt or clogs – Clean and serviceable.

Tires and Tracks

- - Rubber Tracks: Inspected for uniform wear and remaining tread life – Tracks at 85% tread life.
- - Track Alignment: Checked for proper alignment – Aligned, no slippage observed.

Operator Station

- - Joysticks and Controls: Verified responsiveness and accuracy – All controls functional.
- - Seat and Safety Equipment: Inspected seat and seatbelt integrity – Seat in good condition; safety equipment functional.
- - Instrumentation: Gauges, indicators, and warning lights checked – No warning lights; all gauges operational.
- - Visibility: Windows and canopy provide clear visibility – Pass.

Electrical System

- - Battery: Inspected for charge and terminal corrosion – Fully charged; terminals clean.
- - Lighting: Headlights, work lights, and safety lights checked – All lights operational.
- - Wiring: Inspected for damage or loose connections – No issues found.

Bucket and Attachments

- - 66-Inch Bucket: Inspected for wear, cracks, and mounting integrity – Minor wear; structurally sound.
- - Quick Attach System: Verified secure attachment and ease of operation – Fully operational.

Overall Condition

- **Mechanical Condition: 90%**
- **Cosmetic Condition: 85%**
- **Operational Condition: 95%**

This Skidsteer has passed all major inspection points and is considered work-ready