

Albatross Equipment Earthworks

10998 WY-789 Riverton, WY 82501 www.albatrosequipment.com

Inspection Checklist for 2019 Kubota SSV75

Model Name: Kubota SSV75

• **Year**: 2019

Machine Hours: 114Condition: Good



Exterior Condition

• Cab and Operator Compartment:

- o Enclosed ROPS shows no structural damage or dents.
- Glass and seals are intact with no cracks or leaks.
- Doors open and close securely.
- o Paintwork is in good condition with minimal wear.

• Bucket and Attachments:

- o 76" GP bucket is secure with no significant dents, cracks, or rust.
- o Hydraulic quick-attach mechanism operates smoothly without delay.

Mechanical Systems

• Engine Performance:

- Kubota 74.3 HP diesel engine starts promptly with no unusual noise or vibration.
- Engine compartment is clean and dry, with no visible oil, fuel, or coolant leaks.

Hydraulic System:

- Auxiliary hydraulics functional and within specified pressure limits.
- Hoses and fittings inspected—no leaks or wear detected.
- o Hydraulic quick-attach mechanism operates correctly.

• Drive System:

- o Two-speed drive system transitions smoothly between modes.
- o Differential components are operational and in good condition.

Operator Controls and Safety Features

Hand and Foot Controls:

- o Controls are responsive, free of excessive play, and show no damage.
- o Throttle and brake pedals function smoothly.

• Operator Comfort:

- o Cabin features heat, air conditioning, and radio—all fully operational.
- Seat and suspension are intact, with no tears or mechanical faults.

Safety Features:

- o Parking brake engages and disengages securely.
- o Seatbelt is present and in functional condition.
- o Lights and signals are operational.

Undercarriage and Tires

Tires:

- 12-16.5 tires show even tread wear with at least 85% tread remaining.
- No punctures or sidewall damage detected.

Chassis:

 Frame and chassis exhibit no signs of cracking, bending, or prior repairs.

Fluid Levels and Maintenance

Fluids and Filters:

- Engine oil, coolant, and hydraulic fluid levels are within recommended ranges.
- o Filters inspected—no clogs or excessive debris present.

• Fuel System:

- o Fuel tank secure with no leaks or corrosion.
- Fuel lines inspected and in excellent condition.

Final Notes

This 2019 Kubota SSV75 Skidsteer is in **good condition**, with only 114 hours of use. The machine demonstrates excellent operational capability, with no major defects or repairs required. The hydraulic system, drive components, operator controls, and safety features are all fully functional. The tires are in good shape with significant tread remaining, ensuring reliable traction during operation. Minimal cosmetic wear is present, consistent with the machine's hours and usage.