



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2020 Kubota SVL65-2

- Model: 2020 Kubota SVL65-2
- Hours: 1,098
- Condition: Good



Inspection Report

General Condition:

- Skidsteer overall appearance is clean, with no visible dents, cracks, or signs of major damage.
- Paint and finish show typical wear consistent with machine hours, no severe rust or fading observed.

Loader Arms and Attachments:

- Loader arms inspected for cracks, bending, or weld repairs – no issues found.
- Hydraulic Quick Attach system operates smoothly with no delays or leaks.
- New 72" GP bucket securely attached and in excellent condition with no damage or excessive wear.

Hydraulic System:

- Hydraulic fluid levels checked and within the recommended range.
- All hydraulic hoses and fittings inspected – no leaks, cracks, or excessive wear detected.
- Auxiliary hydraulics tested under load – functioning as intended.

Engine and Cooling System:

- 68 HP Kubota diesel engine starts easily and runs smoothly with no unusual noises or vibrations.
- Air filter inspected – clean and serviceable.
- Engine oil level and quality within specifications.
- Cooling system inspected – no leaks, radiator clean and functioning properly.

Undercarriage and Tracks:

- 12.5” rubber tracks show 80% tread remaining, no visible cuts or excessive wear.
- Track tension adjusted and within manufacturer specifications.
- Drive sprockets, idlers, and rollers inspected – no excessive wear or damage noted.

Operator’s Station (OROPS):

- Seat and safety restraints in good condition with no rips or tears.
- Pilot controls tested – responsive and functioning without delay.
- Gauges and indicator lights operational, no error codes displayed.
- Operator Presence System (OPS) tested – functioning as designed.

Transmission and Drivetrain:

- 2-speed transmission shifts smoothly between gears.
- No unusual noises or vibrations during operation.
- Drive motors inspected – operating within normal parameters.

Electrical System:

- Battery terminals clean and securely connected.
- Lights and auxiliary power outlets functional.
- Wiring harnesses inspected – no signs of damage or corrosion.

Operational Tests:

- Machine starts, runs, and shuts down without issue.
- Steering and maneuverability tested – smooth operation in all directions.
- Lift and tilt functions perform well under load with no delays or irregularities.

Conclusion:

The 2020 Kubota SVL65-2 has been thoroughly inspected and is in Good Condition. All systems and components are functional, with no significant issues detected. The machine is work-ready and suitable for immediate use.

Inspector's Note:

This equipment has been maintained to high standards, with all critical components inspected and found in excellent working order. Any future maintenance needs should follow the manufacturer's guidelines for optimal performance and longevity.