

Albatross Equipment Earthworks 10998 WY-789 Riverton, WY 82501 www.albatrosequipment.com

Inspection Checklist for 2020 Kubota SVL75-2



Equipment Details: 2020 Kubota SVL75-2 **Hours**: 2,099 **Condition**: Good

General Condition

- Cab: EROPS cab inspected; glass and seals are intact, no cracks or damage.
- Heat & Air Conditioning: Fully functional; verified performance.
- Radio: Operational with clear audio output.
- Paint: Minor scratches consistent with machine age; no rust or significant damage.

Hydraulic System

- Auxiliary Hydraulics: No leaks or performance issues; flow rates are within specifications.
- Hydraulic Hoses: Inspected for wear, cracks, and leaks; all hoses are in good condition.
- Hydraulic Pump: Operates smoothly with no unusual noises or vibrations.

Loader Arms & Attachments

- Loader Arms: No signs of bending, cracks, or excessive wear; structural integrity verified.
- Hydraulic SSL Quick Attach: Fully functional; secure attachment and detachment of the bucket tested.
- 74" GP Bucket: Shows minor wear but remains structurally sound; cutting edge is in good condition.

Tracks & Undercarriage

- Rubber Tracks (13"): Approximately 75% tread life remaining; wear is even.
- Undercarriage Components: Rollers, idlers, and sprockets are free of damage or excessive wear.
- Track Tension: Correct tension maintained per manufacturer specifications.

Engine & Drivetrain

- Engine: Kubota 74 HP diesel engine inspected; starts smoothly, no unusual noises or vibrations.
- Fluid Levels: Oil, coolant, and hydraulic fluids topped off; no leaks detected.
- Air Filter: Clean and properly seated.
- 2-Speed Transmission: Smooth shifting between speed ranges; no operational concerns.

Electrical System

- Battery: Voltage within specification; terminals clean and secure.
- Lighting: All lights operational, including work lights and indicators.
- Controls: Pilot controls are responsive and free of defects.

Operational Tests

- Lift & Tilt Functionality: Loader operates smoothly under load without hesitation or unusual noise.
- Auxiliary Hydraulics: Tested with auxiliary attachment; performs without issue.
- Travel Performance: 2-speed travel system operates smoothly in all modes; no lag or abnormalities.

Safety Checks

- Parking Brake: Engages and releases properly.
- Emergency Exits: All exits accessible and functional.
- Warning Labels & Decals: Present and legible.

Inspection Summary

The 2020 Kubota SVL75-2 is in **good condition** and ready for work. Minor wear consistent with machine age and usage, but all systems are fully operational. Hydraulic, electrical, and mechanical components meet manufacturer specifications. Tracks and undercarriage are in excellent condition with significant service life remaining.