



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2020 Kubota SVL75-2



Inspected Equipment

Model: 2020 Kubota SVL75-2

Hours: 833

Condition: Good

Features: OROPS, Pilot Controls, 2 Speed, AUX Hydraulics, 74.3 HP Kubota Diesel Engine, New 72" HD Bucket, Hydraulic SSL Quick Attach, 16" Rubber Tracks, 2,282 lbs Lift Capacity, 9,039 lbs Operating Weight

Loader Arms and Boom

- - Loader arms inspected for bending or excessive wear—no structural damage or deformities found.
- - Hydraulic quick attach verified operational with no mechanical defects.
- - Bucket pins and bushings inspected for wear—minimal play noted.
- - New 72" HD bucket attachment confirmed secure and free of defects.

Hydraulic System

- - Hydraulic fluid levels checked and within recommended range.
- - No leaks detected in hydraulic hoses, connections, or cylinders.
- - Auxiliary hydraulics tested for functionality—operating at full capacity with no lag.
- - Pilot controls responsive and free of defects.

Engine

- - 74.3 HP Kubota diesel engine starts smoothly with no unusual noises or vibrations.
- - Engine compartment clean and free of oil or coolant leaks.
- - Air filter inspected and replaced as needed.
- - All belts and hoses in good condition, with no visible cracks or fraying.

Undercarriage and Tracks

- - 16" rubber tracks exhibit uniform wear, with approximately 85% tread life remaining.

- - Track tension verified and adjusted to manufacturer specifications.
- - Sprockets, rollers, and idlers inspected for wear—minimal signs of use.
- - Undercarriage frame checked for cracks or damage—none found.

Electrical and Controls

- - Operator controls responsive and operational.
- - Instrument panel gauges functional and displaying accurate readings.
- - Battery terminals clean and connections secure.
- - Lights and safety features (e.g., horn, warning indicators) tested and operational.

Operator Station (OROPS)

- - Rollover Protective Structure (ROPS) inspected for integrity and compliance.
- - Operator's seat in good condition with no tears or excessive wear.
- - Controls and pedals free of dirt or obstructions.
- - Entry and exit points checked for secure handrails and steps.

Drivetrain

- - 2-speed transmission shifts smoothly and operates as expected.
- - Drive motors inspected—no unusual noises or performance issues.

Overall Condition

- - Exterior panels and paint in good condition, with minor scratches from normal use.
- - Machine levels correctly on flat ground, indicating proper frame alignment.
- - Lift capacity verified at 2,282 lbs without any hydraulic lag.
- - General cleanliness and maintenance indicate routine care.

Inspection Summary

The 2020 Kubota SVL75-2 has been thoroughly inspected and found to be in **Good Condition**, with no significant issues or defects. All major systems, including the hydraulic system, engine, drivetrain, and undercarriage, are fully operational. Minor wear consistent with 833 hours of use was noted but does not affect performance. The machine is work-ready and suitable for immediate deployment.