



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2021 Kubota SCL1000

Equipment Details

- **Model:** 2021 Kubota SCL1000
- **Machine Hours:** 90
- **Condition:** Good
- **Specifications:**
 - Walk Behind w/ Riding Platform
 - Auxiliary Hydraulics
 - 24.8 HP Kubota Diesel Engine
 - 36" General Purpose (GP) Bucket
 - Mini SSL Quick Attach
 - 10" Rubber Tracks
 - 1,000 lbs Lift Capacity
 - 3,035 lbs Operating Weight



Inspection Checklist

General Overview

- **Overall Machine Condition:**
 - Visual inspection confirms good condition. Minor cosmetic wear present consistent with hours of use.
 - No visible damage or unauthorized modifications.

Loader Arms and Bucket

- **Loader Arms:**
 - Checked for structural integrity: No signs of cracks, bending, or excessive wear.
 - Pins and bushings inspected: Tight and properly greased.
- **Bucket:**
 - Inspected for damage: No dents or deformities. Cutting edge in good condition with minimal wear.

- Coupler functionality verified: Smooth attachment and detachment.

Hydraulic System

- **Hydraulic Fluid:**
 - Levels within manufacturer's recommended range.
 - No visible leaks in hoses, connections, or fittings.
- **Auxiliary Hydraulics:**
 - Tested with auxiliary equipment: Full power and no performance issues.
 - Quick couplers in excellent condition.

Tracks and Undercarriage

- **Rubber Tracks:**
 - 10" tracks inspected: Uniform wear with approximately 90% tread remaining.
 - No cracks, cuts, or visible delamination.
- **Undercarriage:**
 - Rollers, idlers, and sprockets in excellent condition. No abnormal wear or damage.

Engine and Powertrain

- **Engine:**
 - 24.8 HP Kubota Diesel Engine runs smoothly. No unusual noises, vibrations, or smoke.
 - Engine oil checked: Proper levels and recently changed.
- **Cooling System:** Radiator and coolant levels inspected: No leaks or overheating.
- **Air Filter:** Clean and free of debris.

Operator Controls and Platform

- **Control Panel:**
 - All switches and gauges function correctly.
 - Hour meter operational and accurate.
- **Riding Platform:**
 - Secure and free of damage. Non-slip surface intact.
 - Safety latches and handles in excellent condition.
- **Joystick Controls:** Fully responsive with no signs of wear or lag.

Electrical System

- **Battery:** Securely mounted, terminals clean and free of corrosion.

- **Lights and Indicators:** All operational, including safety beacons.
- **Wiring Harness:** No exposed or damaged wires.

Performance Tests

- **Lifting Capability:** Lifted maximum rated capacity (1,000 lbs) without issue.
- **Travel System:** Tracks maneuver smoothly forward, backward, and in turns.
- **Hydraulic Pressure:** Tested under load: System operates within manufacturer specifications.

Additional Notes

- **Recommended Maintenance:** Regular greasing of pins and bushings every 50 hours of operation.
- **No Immediate Repairs Necessary:** Machine is work-ready.

Summary of Inspection

The **2021 Kubota SCL1000** is in **good condition**, showing minimal wear consistent with 90 hours of use. All systems are operational, with no leaks, cracks, or major defects. This machine is ready for immediate use in the field.