



**Albatross Equipment Earthworks**  
10998 WY-789 Riverton, WY 82501  
[www.albatrossequipment.com](http://www.albatrossequipment.com)

## **Inspection Checklist for 2021 KUBOTA SCL1000**



### **General Condition**

- Overall Appearance: Equipment shows minimal signs of use; paint and body panels in good condition with minor cosmetic wear consistent with hours.
- Serial Plate: Fully intact and legible.

### **Loader and Boom Assembly**

- Loader Arms: Inspected for bends, cracks, and excessive wear — no issues found.
- Quick Attach Bucket System: Secure and functioning correctly; locking pins engage without issues.
- Bucket Condition: Bucket shows light wear; edges and cutting blade intact with no cracks or excessive dents.

### **Hydraulic System**

- Hydraulic Hoses: Inspected for wear, leaks, and damage — all hoses in good condition.
- Auxiliary Valves: Tested for responsiveness and leak-free operation; all valves functioning as intended.
- Hydraulic Fluid Levels: Fluid level within manufacturer's recommended range; no visible contamination or leaks.

## **Engine**

- Engine Start-Up: Starts smoothly with no unusual noises or vibrations.
- Engine Compartment: Clean and dry; no visible leaks or damage.
- Oil Levels: Checked and found within manufacturer's specifications.
- Air Filter: Inspected and free of debris.

## **Tracks and Undercarriage**

- Rubber Tracks: Tracks exhibit uniform wear with approximately 85% tread remaining; no cuts or damage observed.
- Track Tension: Properly adjusted as per manufacturer's guidelines.
- Undercarriage Components: Rollers, idlers, and sprockets in good condition with no visible wear or damage.

## **Operator Controls and Cabin**

- Control Panel: Fully functional; no error codes displayed.
- Joystick and Pedals: Responsive with no stiffness or excessive play.

## **Electrical System**

- Lights and Indicators: All lights and indicators tested and operational.
- Battery: Tested with proper voltage; terminals clean and secure.

## **Cooling System**

- Radiator: Inspected for debris or damage; no issues detected.
- Coolant Levels: Adequate and within manufacturer's specifications; no leaks.

## **Additional Features**

- Auxiliary Hydraulic Attachments: Fully functional; quick coupling mechanism operates smoothly.
- Safety Features: All safety systems, including seat belt alarm and backup alarm, are in working order.

## **Performance Test**

- Lift and Tilt Functions: Smooth operation with no hesitation or abnormal noises.
- Travel Performance: Tracks provide stable, responsive movement without unusual vibrations.
- Braking System: Effective stopping power with no issues detected.

## **Final Assessment**

The 2021 KUBOTA SCL1000 is in good condition with all primary systems fully operational. Minor cosmetic wear is consistent with 288 operating hours. The equipment is work-ready and meets industry standards for reliability and safety.