

Albatross Equipment Earthworks 10998 WY-789 Riverton, WY 82501 www.albatrosequipment.com

Inspection Checklist for 2023 Kubota SCL1000



Equipment Information

- Model: 2023 Kubota SCL1000

- Hours: 403

- Condition: Good

- Features: Rubber Track, Quick Attach Bucket, Auxiliary Valves

Visual and Structural Inspection

- Loader Arms: No visible signs of bending, cracks, or excessive wear. The structure is intact and operational.
- Chassis and Frame: Inspected for cracks, corrosion, or deformations. Frame is structurally sound and level.
- Paint and Finish: Minimal scratches consistent with machine hours; no rust or significant damage.
- Cab/Operator Station: Clean and intact. All glass and protective covers are free of cracks and damage.

Hydraulic System

- Hoses and Lines: Inspected for wear, cracks, or leaks. No issues detected.
- Auxiliary Valves: Functional, with no hydraulic fluid leakage during testing.
- Hydraulic Fluid Levels: Fluid is within the recommended range, clean, and free of contaminants.

Rubber Tracks and Undercarriage

- Tracks: 85% tread remaining. No cracks, cuts, or excessive wear observed.
- Track Tension: Properly adjusted, ensuring smooth operation.
- Rollers and Idlers: Free of damage and operating correctly.

Engine and Powertrain

- Engine Performance: Smooth startup and operation. No unusual noises, vibrations, or smoke.
- Oil and Coolant Levels: Checked and within manufacturer specifications.
- Exhaust System: Free of soot buildup, cracks, or leaks.

Loader and Attachments

- Quick Attach Mechanism: Operates as intended. Bucket attaches and detaches securely without resistance.
- Bucket Condition: Minimal wear. Edges are sharp and functional, with no cracks or structural damage.
- Loader Boom: Structural integrity is verified. No cracks, excessive wear, or deformations.

Electrical System

- Lights and Indicators: Fully functional, including work lights and safety indicators.
- Battery and Connections: Battery holds a charge and is securely mounted. Terminals are clean and corrosion-free.
- Control Panel: Responsive and error-free during testing.

Operator Controls

- Joystick Controls: Smooth and responsive. No sticking or abnormal resistance.
- Pedals and Levers: Fully functional and free of defects.
- Safety Systems: Emergency stop and seatbelt tested and operational.

Fluids and Filters

- Engine Oil: Fresh and free of contaminants. Filter recently replaced.
- Hydraulic Fluid: Clean and properly filled. Filter is in good condition.

- Fuel System: Inspected for leaks; no issues found.

Additional Checks

- Cooling System: Radiator and hoses are free of blockages and leaks. Coolant is at the appropriate level.
- Air Intake System: Filter is clean and unclogged, ensuring optimal airflow.
- Fan and Belts: Operational, with no fraying or cracks.

Final Assessment

- This 2023 Kubota SCL1000 is in good condition, with components showing normal wear relative to its 403 operating hours.
- It has been thoroughly inspected and is work-ready. No immediate repairs or maintenance required beyond routine service.