

## **Albatross Equipment Earthworks**

# 10998 WY-789 Riverton, WY 82501 www.albatrosequipment.com

# **Inspection Checklist for 2015 JCB 510-56**



## **Mechanical Systems**

## **Engine**

- Engine starts smoothly, no unusual noises.
- No leaks detected.
- - Coolant and oil levels within recommended ranges.
- Exhaust system operating normally.
- Diesel system: No DEF required, operating properly.

#### **Transmission**

- Smooth operation during shifting.
- No delays or hesitations.
- - No leaks detected in the transmission system.

## **Hydraulic System**

- - Hydraulic fluid levels are optimal.
- - No visible leaks in hydraulic lines or cylinders.
- - Boom extends and retracts smoothly without jerking or delays.
- Tilt functionality of forks operates properly.
- Chassis tilt system functioning smoothly.

## **Electrical System**

- All lights are operational (work lights, indicators).
- Wipers in good condition and fully functional.
- - No issues detected in the electrical system.

## **Structural and Functional Components**

#### **Boom and Forks**

- Boom shows no signs of cracks, dents, or non-factory welds.
- - Hydraulic hoses on the boom are free from visible wear or leaks.
- - Forks are straight with no cracks or visible damage.
- - Attachment points are in good condition with no excessive wear.

## **Tires and Suspension**

- - Solid tires show approximately 85% tread remaining.
- - No visible punctures, bulges, or uneven wear.

#### **Steering**

- 3-way steering (front, rear, and crab) tested and functional.
- - No delays or stiffness in the steering response.

## **Safety Features**

- - Safety switches and interlocks function as intended.
- - Load indicator and controls are operational.
- - Maximum lift capacity tested and performs as expected.

#### Cabin

- - Glass: No cracks or broken panels.
- - Controls: Responsive and easy to operate.
- - Visibility: Clear view from the operator's seat.
- - Cabin accessories: A/C, heater, and fan in excellent condition.

### **Conclusion**

This 2015 JCB 510-56 Telehandler has been thoroughly inspected and is in great condition. All systems and components are operational, with no immediate service or repairs required. The machine is ready for work.