



**Albatross Equipment Earthworks**  
10998 WY-789 Riverton, WY 82501  
[www.albatrossequipment.com](http://www.albatrossequipment.com)

## Inspection Checklist for 2018 BOBCAT T595

### Equipment Details:

- Model: 2018 BOBCAT T595
- Machine Hours: 1,337
- Condition: Good
- Specifications:
  - - EROPS with Heat and Air
  - - SJC Controls
  - - 2-Speed Travel
  - - Auxiliary Hydraulics
  - - A71 Package
  - - Rear Weight Kit
  - - 74 HP Doosan Diesel Engine
  - - 68" GP Bucket
  - - Hydraulic SSL Quick Attach
  - - 16" Rubber Tracks
  - - 2,199 lbs Lift Capacity
  - - 8,055 lbs Operating Weight



### Skidsteer Inspection Checklist

#### Operator Cabin

- Inspected ROPS (Roll-Over Protective Structure) – No signs of damage, cracks, or modifications.
- Heat and Air Conditioning system functional – both systems tested and working.
- Seat and seatbelt checked for wear or damage – no issues identified.
- Controls (SJC) verified for smooth operation – all levers and joysticks responsive and free of defects.
- Gauges and display panel functional with no error codes.
- Interior cleanliness and condition assessed – free of debris and in good shape.

#### Hydraulic System

- Hydraulic fluid level checked – within the recommended range.
- Inspected hoses and lines for leaks, cracks, or excessive wear – no issues found.

- Auxiliary hydraulics tested – fully operational with no leaks.
- Hydraulic quick attach mechanism verified – smooth engagement and release.
- A71 package hydraulics functioning correctly.

#### **Engine and Powertrain**

- Engine oil level and quality inspected – oil clean and at the proper level.
- Air filter checked – clean and free of blockages.
- Fuel system inspected for leaks or contamination – no issues found.
- Engine performance tested – runs smoothly with no unusual noises or smoke.
- 2-speed transmission tested – shifts smoothly between speeds.

#### **Loader Arms and Bucket**

- Loader arms inspected for cracks, bends, or welds – no damage present.
- Bushings and pins checked for excessive wear – all within tolerance.
- 68" GP bucket condition assessed – no significant dents or wear; cutting edge in good shape.
- Hydraulic SSL quick attach tested – mechanism operates without delay.

#### **Tracks and Undercarriage**

- 16" rubber tracks inspected for tread wear – approximately 80% tread life remaining.
- Track alignment and tension checked – properly adjusted.
- Undercarriage components inspected for damage or wear – all in good condition.

#### **Electrical System**

- Battery and connections tested – terminals clean and secure.
- Lights and indicators (internal and external) verified – fully operational.
- Horn and safety alarms tested – functioning properly.
- Wiring inspected for signs of fraying or damage – no issues found.

#### **General Appearance**

- Exterior panels inspected for dents, scratches, or rust – minor cosmetic wear consistent with age and hours.
- Decals and safety labels legible and intact.
- Overall cleanliness – machine washed and detailed.

#### **Summary**

The 2018 BOBCAT T595 has been thoroughly inspected and is in Good Condition. The machine is fully operational and work-ready, with no significant issues detected. The rubber tracks and undercarriage show minimal wear, and all major systems, including the hydraulic, engine, and electrical systems, are in excellent working order.