

Albatross Equipment Earthworks

10998 WY-789 Riverton, WY 82501 www.albatrosequipment.com

Inspection Checklist for 2019 BOBCAT T740

Equipment Inspected: 2019 BOBCAT T740

Machine Hours: 1,230

Condition: Good Condition

Features:

- Enclosed ROPS (EROPS) with Heat & Air

- Radio

- SIC Controls

- 2-Speed Travel

- High Flow Auxiliary Hydraulics
- Reversing Fan
- Ride Control
- 74 HP Doosan Diesel Engine
- Hydraulic SSL Quick Attach
- New Bobcat OEM 80" HD Bucket
- 18" Rubber Tracks
- 3,200 lbs Lift Capacity
- 10,127 lbs Operating Weight



General Condition

- - Exterior Condition: Minimal cosmetic wear consistent with machine age. Paint in good condition with no major scratches, dents, or rust.
- Cabin Condition: Clean and well-maintained. Heat, air conditioning, and radio functioning as intended. Operator seat and controls in excellent shape with no visible wear or damage.

Loader Arms and Boom

• - Structural Integrity: Inspected for cracks, bends, or welds. None found. Loader arms in solid condition.

 - Pins and Bushings: Checked for excessive play or wear. Found to be within acceptable tolerances.

Hydraulic System

- Hydraulic Lines and Hoses: No visible leaks, cracks, or wear on hoses. Connections are secure.
- Hydraulic Fluid Levels: Fluid levels within manufacturer's recommended range.
- - Auxiliary Hydraulics: High flow auxiliary hydraulics tested and functioning perfectly.

Engine and Powertrain

- - Engine Performance: Doosan diesel engine starts smoothly, operates without unusual noises, vibrations, or smoke.
- - Cooling System: Reversing fan operational, and no overheating observed during testing.
- - Filters: Air and oil filters recently serviced and clean.
- - Oil Levels: Oil level checked and found within recommended range.

Tracks and Undercarriage

- - Rubber Tracks: New 18" rubber tracks installed, exhibiting 100% tread life.
- - Track Tension: Verified and adjusted to manufacturer's specifications.
- Rollers and Idlers: Inspected and found to be in excellent working condition with no signs of wear.

Operator Controls

- - SIC Controls: Responsive and free of defects. No lag or sticking observed.
- - Indicators and Gauges: All dashboard indicators and gauges operational, including speed, hydraulic pressure, and engine temperature.
- - Lights: Front and rear lights functional.

Bucket and Quick Attach System

- Bucket Condition: New 80" heavy-duty Bobcat OEM bucket with no signs of use or wear.
- - Hydraulic SSL Quick Attach: Tested and functioning smoothly for secure and efficient bucket attachment.

Additional Features

- - 2-Speed Travel: Tested and transitions smoothly between speeds.
- Ride Control: Verified operational, reducing bounce and enhancing operator comfort.

Overall Evaluation

The 2019 BOBCAT T740 is in good condition and ready for immediate use. All systems, including hydraulics, powertrain, and operator controls, are functional with no issues. The machine has been well-maintained and equipped with new rubber tracks and a new 80" HD bucket. Minor cosmetic wear is present but does not affect performance.

Recommendations

- Continue regular maintenance to preserve condition and performance.
- Monitor hydraulic system for any potential wear over time due to age.