

Albatross Equipment Earthworks 10998 WY-789 Riverton, WY 82501 www.albatrosequipment.com

Inspection Checklist for 2020 TAKEUCHI TL10V2

Model: 2020 TAKEUCHI TL10V2

Machine Hours: 618 **Condition**: Good



1. General Condition

- Cab: EROPS (Enclosed Roll-Over Protective Structure) shows no signs of damage or structural weakness. Heat and air conditioning are fully functional. Radio operates as expected.
- **Appearance**: Paint is intact with minor cosmetic wear. Decals are legible. No significant rust or corrosion observed.
- **Operator Seat**: Comfortable and in good condition. No tears or excessive wear.

2. Engine and Performance

- **Engine Model**: 74.3 HP Kubota Diesel
- Engine starts smoothly without delays. Idles consistently with no unusual noises, smoke, or vibrations.
- Oil levels and condition: Checked and within recommended range. No signs of contamination or leaks.
- Fuel system: No leaks detected in lines or filters. Fuel filter appears clean.

3. Hydraulic System

- **Auxiliary Hydraulics**: Standard flow system is fully functional and shows no signs of leaks. Hoses and connectors are free of wear or damage.
- Hydraulic Fluid Levels: Checked and within acceptable range. No contamination detected.
- Hydraulic quick attach system operates smoothly, securely locking and releasing the bucket.

4. Loader and Boom Assembly

- Loader arms are straight and show no signs of bending, cracking, or excessive wear.
- Pivot points are properly greased and free of excessive play.
- New 72" heavy-duty bucket is securely mounted and shows no damage. Cutting edge is intact with no excessive wear.

5. Undercarriage and Tracks

- **Tracks**: 16" rubber tracks show uniform wear with approximately 85% tread life remaining. No cuts, cracks, or uneven wear observed.
- Rollers, idlers, and sprockets are in good condition with no visible damage or excessive wear.
- Track tension is properly adjusted.

6. Electrical and Controls

- **Pilot Controls**: Responsive, smooth, and free of lag. All functions operate correctly.
- Instrument panel and display: Fully operational with no error codes or warnings.
- Lighting: All exterior lights, including work lights, function properly.
- Backup camera provides a clear image with no visual obstructions.
- Horn and other electrical components (wipers, switches, etc.) work as intended.

7. Two-Speed System

• Two-speed operation engages and shifts smoothly between ranges. No unusual noises or delays.

8. Safety Features

- Seat belt and safety lockouts are in place and operational.
- ROPS meets safety standards with no modifications or damage.
- Warning labels are intact and legible.

9. Fluids and Filters

• Engine oil, hydraulic fluid, coolant, and other fluids are checked and within specifications. Filters are clean and do not require immediate replacement.

10. Miscellaneous

- Operating weight: Verified at 10,270 lbs.
- Rated lift capacity: 2,522 lbs confirmed with no degradation in performance.
- No unusual vibrations or noises during operation.

Overall Assessment

The 2020 TAKEUCHI TL10V2 skid steer with 618 hours is in **good condition**, demonstrating reliable performance with minimal cosmetic wear and no major mechanical issues. All systems, including the engine, hydraulics, undercarriage, and operator controls, function as intended. The new 72" heavy-duty bucket enhances the machine's operational capabilities. This skid steer is ready for immediate use in demanding applications.