



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2021 BOBCAT T64

Model: 2021 BOBCAT T64

Hours: 196

Condition: Good



Structural Integrity

Loader Arms: Inspected for bending, cracks, and excessive wear - No issues detected .

Chassis & Frame: Verified structural integrity and level stance - No visible damage or misalignment .

Cabin (EROPS): Checked for any cracks or damage in the protective structure - In excellent condition .

Hydraulic System

Hydraulic Fluid Levels: Inspected and found within the manufacturer's recommended range - No leaks detected .

Hydraulic Hoses & Connections: Checked for signs of wear, cracks, and leaks - No issues found .

Quick Attach Mechanism: Tested hydraulic quick attach functionality - Operates smoothly without defects .

Tracks & Undercarriage

Rubber Tracks: Inspected for uniform wear and remaining tread life - Approximately 85% tread remaining, no cracks or tears .

Undercarriage Components: Checked rollers, idlers, and sprockets for wear - All components in good working condition .

Track Tension: Verified proper tension - Adjusted to specification .

Engine & Powertrain

Engine Operation: Smooth start and idle, no unusual noises or vibrations - Runs well .

Oil Levels: Checked engine oil levels and quality - Oil is clean and within recommended range .

Cooling System: Inspected radiator and coolant levels - No leaks or overheating issues detected .

Transmission: Verified smooth operation of drive system - No performance issues .

Operator Controls & Safety Systems

Control Responsiveness: Tested joystick and foot controls - Fully responsive, no lag or sticking .

Safety Features: Inspected seatbelt, safety bar, and backup alarm - All systems functional .

Instrumentation Panel: Verified gauges and warning lights - All operational .

Climate Control: Tested heating and air conditioning (EROPS) - Both systems functional .

Bucket & Attachments

Hydraulic Quick Attach Bucket: Inspected for wear and functionality - Attachment operates correctly, no visible damage .

Bucket Condition: Verified structural integrity and cutting edge - Good condition, minimal wear .

Electrical System

Battery Condition: Tested battery voltage and terminals - Battery in good condition, no corrosion .

Lighting System: Verified operation of all lights (work lights, safety lights) - All lights functioning properly .

Summary of Condition

The 2021 BOBCAT T64 with 196 hours is in good condition . All inspected components are functional and meet operational standards. The rubber tracks show minimal wear with approximately 85% tread remaining. Hydraulic systems, engine, and operator controls are in excellent working order. The machine is ready for immediate use with no major issues identified.

This Skidsteer has been thoroughly inspected by a professional mechanic, ensuring it is work-ready and reliable.