



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2019 BOBCAT T595

Equipment Information

Model Name: 2019 Bobcat T595

Machine Hours: 484

Condition: Good

Specifications:

- Enclosed ROPS with Heat & Air Conditioning
- Hand & Foot Controls
- AUX Hydraulics (A51 Package)
- 74 HP Doosan Diesel Engine
- 74" Tooth Bucket
- Hydraulic SSL Quick Attach
- 13" Rubber Tracks
- 2,199 lbs Lift Capacity
- 8,055 lbs Operating Weight



Inspection Checklist

Exterior and Structural Integrity

- Loader Arms: Inspected for cracks, bends, or excessive wear—structurally sound with no visible damage.
- Bucket: Checked for dents, cracks, or excessive wear—74" tooth bucket in good condition with minor cosmetic wear.

- Hydraulic Quick Attach: Mechanism operates smoothly and locks securely—no issues detected.
- Body Panels: Inspected for rust, dents, and other damage—panels in good shape, minor scratches consistent with use.
- ROPS (Enclosed Cab): Frame checked for structural integrity—clean and damage-free.

Hydraulic System

- Hydraulic Hoses and Lines: No visible leaks, cracks, or excessive wear—hoses and fittings are secure.
- Auxiliary Hydraulics: Functionality tested—responsive and operating as expected.
- Hydraulic Fluid Levels: Fluid levels within manufacturer-recommended range—fluid clean with no contamination.

Undercarriage and Tracks

- Rubber Tracks (13"): Inspected for wear, cuts, or uneven tread—tracks in good condition with approximately 85% tread life remaining.
- Track Tension: Verified proper tension—adjusted to specifications.
- Rollers and Idlers: Inspected for wear, damage, or unusual noise during operation—all components in good working condition.

Engine and Powertrain

- Engine (74 HP Doosan Diesel): Started smoothly with no unusual noises or vibrations—operates efficiently under load.
- Oil and Fluids: Checked engine oil, coolant, and transmission fluid—levels and quality within specifications.
- Exhaust System: Inspected for leaks or damage—no issues detected.
- Cooling System: Radiator and coolant system free of debris and functioning effectively—temperature remains stable during operation.

Operator Controls and Cabin

- Hand & Foot Controls: Tested for responsiveness—controls are smooth and precise.
- A/C and Heating System: Fully operational—provides consistent airflow and temperature control.
- Radio: Functional and free of defects.
- Seat and Interior: Checked for damage or excessive wear—interior clean and well-maintained.

Electrical System

- Battery: Voltage within range, terminals clean and connections secure.
- Lights: All lights (including work lights) tested—functional with no bulb replacements required.
- Dashboard Indicators: No active warning lights or error codes present on the display.

Performance Test

- Lifting Mechanism: Tested loader boom and arms—lifts, tilts, and lowers smoothly under load.
- Drive System: Tested forward, reverse, and turning—machine responds promptly with no lag or hesitation.
- Parking Brake: Engages and disengages as expected—secure when activated.

Inspection Summary

The 2019 Bobcat T595 is in good condition, with all systems operational and components exhibiting minor wear consistent with 484 operating hours. The machine has been well-maintained, with no leaks, structural damage, or functional defects detected. Tracks and hydraulic systems show excellent performance, and the cab is clean and fully operational.

Condition Rating: 90% (Minor cosmetic wear only)

This Skidsteer is ready for immediate use in a work environment, requiring no additional maintenance at this time.