



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2019 BOBCAT T590



General Condition

- Loader arms inspected for bending, cracks, or excessive wear: No issues found.
- Frame and chassis inspected for structural integrity: Solid and stable, no damage detected.
- Paint condition: Minor scratches consistent with age and use.

Hydraulic System

- Hydraulic hoses and connections: No leaks or visible wear.
- Fittings checked for secure attachment: All secure.
- Hydraulic fluid levels: Levels adequate and fluid clean.

Engine and Powertrain

- Engine oil level and condition: Oil level optimal, no signs of contamination.
- Checked for unusual noises during operation: Runs smoothly, no unusual noises.
- Exhaust inspected for smoke or odor: Clean exhaust, no irregularities.
- Cooling System: Radiator clean and functional, coolant level sufficient.

Operator Station

- Controls and Gauges: All controls responsive and functional.
- Operator seat and restraint system in good condition.
- Safety features (lap bar, seat belt) fully operational.

Attachment and Auxiliary Systems

- Hydraulic quick-attach system tested: Smooth operation, no issues.
- Bucket condition (wear and cutting edge): Normal wear, cutting edge intact.
- Auxiliary valve operation: Functions as intended.

Undercarriage and Tracks

- Rubber tracks inspected for wear and cracking: Good condition with uniform wear.
- Tension checked and adjusted: Tension optimal.
- Rollers and drive components inspected for damage: All components in working order.

Electrical System

- Battery terminals clean and secure: No corrosion or loose connections.
- Battery voltage checked: Voltage within acceptable range.
- Lighting and Indicators: All lights functioning.

Tires and Fluid Checks

- Checked fuel, engine oil, hydraulic fluid, and coolant: All levels adequate.
- Verified no leaks around reservoirs: No leaks detected.

Overall Condition Assessment

The 2019 BOBCAT T590 has been thoroughly inspected and is deemed to be in Good Condition. The machine shows minimal wear consistent with its 974 operational hours. All systems, including hydraulic, engine, and operator controls, are fully functional, with no major issues detected. Loader arms, tracks, and auxiliary systems meet manufacturer specifications, with minor cosmetic blemishes that do not impact functionality. This Skidsteer is work-ready and has passed all inspection points with no need for immediate maintenance.