



**Albatross Equipment Earthworks**  
10998 WY-789 Riverton, WY 82501  
[www.albatrossequipment.com](http://www.albatrossequipment.com)

## Inspection Checklist for 2019 BOBCAT T595

### \*\*Equipment Details\*\*

- \*\*Model\*\*: 2019 BOBCAT T595
- \*\*Hours\*\*: 951
- \*\*Condition\*\*: Good
- \*\*Specifications\*\*:
  - Open ROPS (OROPS)
  - 74 HP Doosan Diesel Engine
  - SJC Controls
  - Auxiliary Hydraulics
  - Rear Weight Kit
  - 74" Tooth Bucket with SSL Quick Attach
  - 12" Rubber Tracks
  - 2,199 lbs Lift Capacity
  - 8,055 lbs Operating Weight



### \*\*Inspection Checklist\*\*

#### 1. General Exterior Condition

- - Paint: Minor scratches consistent with normal use; no rust or corrosion.
- - Loader Arms: Structurally sound, no bends, cracks, or deformations.
- - Decals: Legible and intact.
- - OROPS Frame: Free of damage or distortion; all bolts secure.

#### 2. Hydraulic System

- - Hydraulic Hoses and Lines: No visible leaks, cracks, or wear.
- - Auxiliary Hydraulics: Operational, with connections in good condition.
- - Hydraulic Fluid Levels: Within manufacturer's recommended range.
- - Cylinders: Smooth operation, no leaks or pitting.

#### 3. Engine and Powertrain

- - Engine Start: Starts smoothly, idles without unusual noises or smoke.
- - Engine Compartment: Clean and dry; no oil or coolant leaks detected.
- - Air Filter: Checked and in good condition.

- - Exhaust System: Secure and free of visible damage or leaks.
- - Fuel System: No leaks or damage; connections secure.

#### 4. Undercarriage and Tracks

- - Tracks: 12" rubber tracks exhibit even wear with approximately 75% tread remaining.
- - Track Tension: Properly adjusted, no signs of excessive slack or wear.
- - Rollers and Idlers: Functional with no excessive wear or damage.

#### 5. Bucket and Attachments

- - 74" Tooth Bucket: Teeth intact; minor wear consistent with use.
- - SSL Quick Attach: Operates smoothly and securely locks bucket in place.

#### 6. Operator Controls and Interior

- - SJC Controls: Fully operational, responsive, and free of defects.
- - Seat and Safety Restraints: Good condition, no tears or excessive wear.
- - Throttle and Pedals: Functional with no sticking or lag.
- - Warning Lights and Gauges: All functioning and displaying correctly.
- - Operator Manual Holder: Present and secure.

#### 7. Electrical System

- - Battery and Connections: Secure, terminals free of corrosion.
- - Lighting System: All lights operational, including safety lights.
- - Wiring: No visible damage, fraying, or loose connections.

#### 8. Fluids and Maintenance

- - Oil Levels: Engine oil within acceptable range; clean with no contaminants.
- - Coolant Levels: Checked and within specification.
- - Filters: Recently replaced or in good condition.
- - Maintenance Records: Up-to-date with no overdue service intervals.

#### 9. Safety Features

- - Parking Brake: Engages and releases correctly.
- - Backup Alarm: Operational.
- - Operator Restraints: Functional and secure.

### **\*\*Summary of Inspection\*\***

The 2019 BOBCAT T595 with 951 hours is in **\*\*Good Condition\*\***. The Skidsteer has been thoroughly inspected, and all systems are operational with no major issues detected. Routine wear consistent with the reported hours is present but does not affect functionality. The hydraulic system, engine, and operator controls are in excellent working order. Tracks show approximately 75% life remaining, and all attachments are functional. Minor cosmetic imperfections noted on the paintwork.

This Skidsteer is ready for immediate use in work environments. No significant repairs or maintenance are required at this time.