



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2021 DEERE 26G



Boom, Arm, and Bucket Inspection

- Boom and Arm Condition: No visible cracks or structural damage. Hydraulic cylinders free of leaks and fully operational.
- Bucket: 24" bucket shows minimal wear, teeth are intact and sharp. Coupler connection secure, no excessive play.
- Hydraulic Thumb: Operates smoothly, no leaks at hydraulic connections.

Hydraulic System

- Hydraulic Fluid Levels: Fluid at recommended levels, no contamination or discoloration.
- Hoses and Lines: All hydraulic hoses in good condition, no visible wear, cracks, or leaks.
- Hydraulic Pump and Cylinders: Pump operating efficiently with no unusual noises. Cylinders are clean, functioning properly, and free of excessive wear.

Undercarriage Condition

- Tracks: Rubber tracks are in excellent condition, approximately 95% life remaining. No cracks, cuts, or significant wear on rubber.
- Sprockets and Rollers: Sprockets and rollers show minimal wear, no damage or misalignment.
- Track Tension: Tension is within specifications, properly adjusted.

Swing Drive and Motor

- Swing Drive Operation: Motor operates smoothly with no unusual noises or jerking.
- Swing Bearing: Free of play, grease points adequately lubricated.

Engine Condition

- Engine Oil: Oil level checked, within normal range. No contamination or excessive wear indicators.
- Filters: Air and oil filters are clean and in good condition.
- Performance: Engine starts easily, idles smoothly, and shows no unusual noises or smoke during operation.
- Exhaust System: Free of leaks or damage. No visible soot buildup or blockages.

Cab Condition

- Operator's Cabin (OROPS): Clean and well-maintained. All controls and gauges are functional.
- Visibility: Clear sightlines, no obstructions.
- HVAC System: N/A (Open ROPS does not include HVAC).

Push Blade

- Condition: Blade shows minor wear consistent with usage, edges are sharp and straight.
- Operation: Moves freely and smoothly, no leaks in hydraulic connections.

Auxiliary Hydraulics

- Valves and Connections: Auxiliary hydraulics operational, no visible leaks or damage to connections.

Inspection Summary

The 2021 DEERE 26G is in good condition with minimal wear and tear due to low operating hours. The rubber tracks, hydraulic systems, and engine components are well-maintained and in excellent working order. All inspected components meet operational standards, and the machine is fully operational without requiring immediate maintenance or repairs.