



**Albatross Equipment Earthworks**  
10998 WY-789 Riverton, WY 82501  
[www.albatrossequipment.com](http://www.albatrossequipment.com)

## Inspection Checklist for 2017 BOBCAT T750



### General Overview

#### Exterior Condition:

- Paint and body panels are intact with minor cosmetic blemishes.
- No visible rust, dents, or significant wear.

#### Serial Number Plate:

- Clearly visible and legible.

### Loader Arms and Attachments

#### Loader Arms:

- Inspected for cracks, bends, or weld repairs — No issues found.
- Pins and bushings checked for excessive wear — Minimal wear, in line with machine hours.

#### Hydraulic Coupler:

- Mechanism operates as expected; allows attachment changes without leaving the seat.
- No leaks or damage observed.

#### Self-Leveling Loader:

- System functions smoothly and consistently.

### Hydraulic System

### **Hoses and Fittings:**

- Checked for leaks, cracks, or bulges — No issues detected.

### **Hydraulic Cylinders:**

- Free of leaks and operational during extension and retraction.

### **Hydraulic Fluid Levels:**

- Checked and found within manufacturer-recommended range.

## **Undercarriage**

### **Tracks:**

- Rubber tracks exhibit approximately 85% tread remaining.
- Checked for cracks, cuts, or missing lugs — No damage noted.

### **Track Rollers and Idlers:**

- Inspected for excessive wear and proper alignment — Good condition.

## **Engine and Powertrain**

### **Engine Condition:**

- Starts easily and operates smoothly; no unusual noises or vibrations.
- Checked for leaks, oil levels, and cleanliness — No issues identified.

### **2-Speed Travel System:**

- Engages smoothly; both speeds tested and function as expected.

### **Exhaust System:**

- Free of leaks; emissions appear normal.

## **Operator's Cabin**

### **Premium Panel and Joystick Controls:**

- Controls are responsive and intuitive; no defects noted.
- Panel displays operational data clearly.

### **Cab Interior:**

- Clean and well-maintained.
- Seat and restraint systems are in good condition.
- No broken or cracked glass.

**Visibility:**

- Excellent; mirrors and windows are clean and clear.

## **Electrical System**

**Battery:**

- Holds charge; terminals are clean and connections secure.

**Lights:**

- All operational (work lights, safety lights, etc.).

**Horn and Alarms:**

- Functional.

## **Fluids and Filters**

**Oil Levels:**

- Engine oil checked and within specifications.

**Filters:**

- Air and oil filters in good condition.
- No signs of clogging or excessive dirt.

**Coolant Levels:**

- Adequate; no leaks detected.

## **Additional Features**

**Hydraulic Auxiliary Hookups:**

- Inspected for proper functioning — All hookups operational with no leaks.

**Performance in Use:**

- Machine demonstrates smooth operation with no delays or interruptions during inspection.

## **Inspection Summary**

This 2017 BOBCAT T750 is in good condition and has been meticulously inspected. The hydraulic system, loader arms, engine, and cabin controls are all functioning as expected. Tracks and undercarriage components show normal wear consistent with the machine's hours. Minimal cosmetic blemishes are present but do not affect functionality. This unit is ready to work and demonstrates the reliability and performance expected of Bobcat equipment. Buyers can expect a well-maintained and operational skid steer.