



**Albatross Equipment Earthworks**  
10998 WY-789 Riverton, WY 82501  
[www.albatrossequipment.com](http://www.albatrossequipment.com)

## **Inspection Checklist for 2018 BOBCAT S770**

Model: 2018 BOBCAT S770

Machine Hours: 1,032

Condition: Good Condition

Features:

- EROPS with Heat & Air
- A91 Package
- Hand & Foot Controls
- 2-Speed Travel
- High Flow Auxiliary Hydraulics
- 92 HP Doosan Diesel Engine
- Hydraulic SSL Quick Attach
- New Bobcat OEM 74" General Purpose (GP) Bucket
- 12-16.5 Tires
- Lift Capacity: 3,350 lbs
- Operating Weight: 9,314 lbs



### **Exterior Condition**

- Loader Arms: Inspected for cracks, welds, or excessive wear – No issues found.
- Paint & Decals: Inspected for chips, fading, or scratches – Minor cosmetic scratches noted.

- Frame & Chassis: Checked for signs of damage, rust, or deformities – No damage or rust detected.

### **Cabin and Operator Controls**

- Cab Interior: Inspected for cleanliness and functionality – Cab clean and well-maintained.

- Controls: Verified hand and foot controls – Responsive and functioning correctly.

- HVAC System: Tested heat and air conditioning – Operating effectively.

- Visibility: Checked glass, wipers, and mirrors – No cracks or visibility issues.

### **Hydraulic System**

- Hydraulic Hoses & Connections: Inspected for leaks or wear – No leaks or cracks found.

- High Flow Auxiliary Hydraulics: Tested for performance – Functioning as expected.

- Hydraulic Fluid Levels: Checked for proper levels – Within recommended range.

### **Engine & Powertrain**

- Engine Performance: Verified smooth operation with no unusual noises or vibrations – Engine runs smoothly.

- Fluid Levels: Checked oil, coolant, and fuel – All fluids topped off and clean.

- Exhaust System: Inspected for leaks or abnormal emissions – No issues found.

- Battery & Electrical Systems: Checked voltage, connections, and overall health – Battery in good condition.

### **Tires & Undercarriage**

- Tire Condition: Inspected 12-16.5 tires for wear and pressure – Tread at 75%, pressure within specifications.

- Wheel Hubs & Bearings: Checked for damage or looseness – No abnormalities found.

### **Bucket & Attachments**

- New 74" GP Bucket: Inspected for structural integrity – Bucket in excellent condition.

- Quick Attach System: Verified smooth attachment and detachment – Fully operational.

### **Performance Testing**

- Two-Speed Travel: Tested in both speeds – Functions properly in all ranges.

- Lift Mechanism: Tested lifting, holding, and lowering – Performs efficiently with no drift.
- Braking System: Verified brakes in forward and reverse – Responsive and reliable.

### **Final Assessment**

The 2018 BOBCAT S770 is in good overall condition with 1,032 hours. All major systems, including the engine, hydraulic system, and operator controls, were inspected and found to be in excellent working order.

Minor cosmetic scratches are present but do not impact performance. The tires show 75% tread life remaining, and all attachments, including the new OEM 74" GP bucket, are in excellent condition.

This Skidsteer is work-ready and requires no immediate maintenance or repairs. It is a dependable machine suitable for a variety of tasks, offering high performance and reliability.