



**Albatross Equipment Earthworks**  
10998 WY-789 Riverton, WY 82501  
[www.albatrossequipment.com](http://www.albatrossequipment.com)

## Inspection Checklist for 2018 BOBCAT T740

Model: 2018 BOBCAT T740

- Hours: 1,708
- Condition: Good
- Features:
  - Enclosed ROPS with Heat & Air
  - SJC Controls
  - Auxiliary Hydraulics
  - 74 HP Doosan Diesel Engine
  - 80" GP Bucket
  - SSL Quick Attach
  - 18" Rubber Tracks
  - 3,200 lbs Lift Capacity
  - 10,127 lbs Operating Weight



### 1. Exterior Condition

- **Cab Structure:** No dents, cracks, or structural deformities in EROPS; glass intact with no visible cracks or chips.
- **Paint and Coating:** Minor surface wear consistent with hours; no rust or significant scratches noted.
- **Loader Arms:** No bends, cracks, or excessive wear. Pivot points inspected and in good condition.

### 2. Hydraulic System

- **Hoses:** Inspected for leaks, wear, and cracks; all hoses are in good condition with secure fittings.
- **Auxiliary Hydraulics:** Tested for full functionality; delivers adequate flow and pressure.
- **Hydraulic Fluid:** Levels checked and within the recommended range; no contamination or leaks.

### 3. Tracks and Undercarriage

- **Rubber Tracks:** 18" tracks exhibit uniform wear with approximately 75% tread remaining; no cracks or separations.
- **Rollers and Idlers:** Rollers and idlers are in good condition; no excessive wear or noise during operation.
- **Track Tension:** Adjusted to manufacturer specifications.

#### 4. Engine and Powertrain

- **Engine Performance:** 74 HP Doosan diesel engine starts smoothly and runs without unusual noises or vibrations.
- **Fluids:**
  - Engine oil level within recommended range, recently serviced.
  - Coolant level checked; no signs of leaks or overheating.
  - Fuel system free of contamination.
- **Belts and Filters:** Inspected for wear; no cracks or damage observed.
- **Exhaust System:** Secure and free of leaks or rust.

#### 5. Operator Controls

- **SJC Controls:** Joystick controls are responsive and functional; no stickiness or delays observed.
- **Display Panel:** Operational and free of error codes; all indicators functioning as expected.
- **Switches and Levers:** All switches and levers tested; no defects or malfunctions.

#### 6. Bucket and Attachments

- **80" GP Bucket:**
  - Cutting edge exhibits moderate wear, but still serviceable.
  - Bucket mounts secure and free of cracks or weld repairs.
- **SSL Quick Attach:** Mechanism operates smoothly; locks securely in place.

#### 7. Electrical Systems

- **Lights:** Front and rear lights operational with no broken lenses.
- **Battery:** Voltage within recommended range; terminals clean and secure.
- **Wiring:** Inspected for damage or wear; no issues found.

#### 8. Interior Condition

- **Seats and Controls:** Seat upholstery in good condition with no tears; seat adjustments functional.
- **HVAC System:** Heat and air conditioning provide adequate cooling and heating.
- **Cab Cleanliness:** Interior is clean and free of debris; floor mats intact.

## 9. Safety Features

- **ROPS Integrity:** Inspected and structurally sound.
  - **Horn and Backup Alarm:** Functional and audible.
  - **Safety Locks:** Loader arm safety lock tested and operational.
- 

## Inspection Summary

The **2018 BOBCAT T740** is in **good condition** with all systems functional. No significant issues or defects detected. The machine is ready for immediate work and meets operational and safety standards.

---