



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2018 DEERE 317G

Equipment Details:

Model: 2018 DEERE 317G

Hours: 782

Condition: Good

Specifications:

- - EROPS (Enclosed ROPS)
- - 61 HP Yanmar Diesel Engine
- - Heat & Air
- - SJC Controls (Selectable Joystick Controls)
- - Auxiliary Hydraulics
- - Rear Weight Kit
- - 72" High-Capacity Bucket
- - Hydraulic SSL Quick Attach
- - 16" Rubber Tracks
- - 2,125 lbs Lift Capacity
- - 8,195 lbs Operating Weight



Inspection Results

Loader Arms & Boom

- - Inspected loader arms for signs of bending, cracks, or excessive wear: No issues found.
- - Checked pivot points and pins for looseness or wear: In good condition.
- - Verified bucket attachment mechanism (Hydraulic SSL Quick Attach): Secure and operational.

Hydraulic System

- - Checked hydraulic hoses for leaks, cracks, or wear: No leaks or damage.
- - Verified hydraulic fluid levels: Within recommended range.

- - Tested auxiliary hydraulics functionality: Operating smoothly.

Engine & Powertrain

- - Inspected engine for oil leaks or signs of wear: Clean and well-maintained.
- - Verified smooth engine operation with no unusual noises or vibrations: Engine runs smoothly.
- - Confirmed engine power matches specifications (61 HP Yanmar Diesel): Within parameters.
- - Checked transmission and drivetrain for any irregularities: No issues detected.

Tracks & Undercarriage

- - Inspected 16" rubber tracks for wear and uniform tread depth: Good condition with minimal wear.
- - Verified track tension is within manufacturer's specifications: Correct tension maintained.
- - Inspected rollers and sprockets for wear or damage: No signs of significant wear.

Operator Cab & Controls

- - Checked EROPS for structural integrity: Cab frame is solid with no damage.
- - Verified heat and air conditioning systems: Fully operational.
- - Inspected SJC controls for responsiveness and smooth operation: Controls are precise and functional.
- - Tested all dashboard indicators and gauges: Accurate and operational.

Electrical System

- - Verified functionality of lights (work lights, safety lights): All lights are functional.
- - Checked battery condition and terminal connections: Battery is charged and securely connected.

Attachments

- - Inspected 72" high-capacity bucket for structural integrity and edge wear: Bucket is in excellent condition.
- - Verified quick attach mechanism for ease of use and security: Mechanism functions as intended.

General Maintenance

- - Checked fluid levels (engine oil, coolant, hydraulic fluid): All fluids topped off and clean.
- - Verified rear weight kit is securely attached: No issues noted.
- - Inspected overall machine cleanliness and body panels: Clean with minimal cosmetic wear.

Overall Condition Assessment:

The 2018 DEERE 317G is in good condition, with all systems operational and no significant wear or damage. This skid steer is well-maintained and ready for work.

Inspector Notes:

This machine is suitable for immediate use in demanding job site conditions. Routine maintenance should be performed according to the manufacturer's schedule to maintain reliability.