



**Albatross Equipment Earthworks**  
10998 WY-789 Riverton, WY 82501  
[www.albatrossequipment.com](http://www.albatrossequipment.com)

## Inspection Checklist for 2018 Kubota SSV75

- **Make/Model:** 2018 Kubota SSV75
- **Machine Hours:** 437 Hours
- **Condition:** Good Condition



### Exterior Condition:

- **Loader Arms:** Inspected for structural integrity; no cracks, bends, or excessive wear detected.
- **Bucket:** 74" GP bucket shows no significant dents or wear; edges are in good condition with minimal signs of use.
- **Paint:** Surface paint is intact with minor cosmetic scratches, typical for usage.
- **Cab Enclosure:** EROPS inspected; no visible damage to frame, glass, or seals.

### Engine and Powertrain:

- **Engine Performance:** Engine starts smoothly and runs without unusual noises or vibrations.
- **Oil Levels:** Engine oil levels within recommended range; no signs of contamination or leaks.
- **Cooling System:** Radiator and cooling fan inspected; no blockages or leaks found.
- **Two-Speed Transmission:** Tested for functionality; shifts between speeds smoothly.

### Hydraulics:

- **Hydraulic Hoses and Fittings:** Inspected for wear, cracks, or leaks; all components are secure and in good condition.
- **Auxiliary Hydraulics:** Fully operational with no performance issues noted.

- **Hydraulic Fluid Levels:** Checked and confirmed within optimal range.

### Tires and Undercarriage:

- **Tires:** 12-16.5 tires show approximately 85% tread remaining; no cuts or sidewall damage detected.
- **Wheel Hubs and Bearings:** Inspected for wear and play; no issues identified.

### Operator Station:

- **Controls:** Pilot controls responsive and functioning as designed.
- **Seat and Interior:** Seat and cabin interior are clean with no significant damage or wear.
- **Climate Control:** Heat and air conditioning tested; both systems function properly.
- **Radio:** Operational without issues.
- **Rear Camera:** Tested and functioning correctly, providing clear visibility.

### Electrical Systems:

- **Lighting:** All external lights, including work lights and indicators, tested and operational.
- **Battery:** Voltage tested; battery holds charge and connections are secure.
- **Electrical Components:** Wiring inspected for damage; no issues detected.

### Performance Test:

- **Lifting Capacity:** Tested under load; lifts to maximum capacity of 2,690 lbs without difficulty.
- **Steering and Maneuverability:** Machine steers smoothly with no unusual noises or resistance.
- **Braking System:** Brakes tested; responsive and within safety standards.
- **Operating Weight:** Confirmed as per specifications; no modifications affecting balance.

### General Observations:

- The machine is in good condition with no major defects or performance issues.
- All key systems are fully operational, and maintenance appears up-to-date.
- Recommended minor cosmetic touch-ups for surface scratches.

---

### Inspection Summary:

The **2018 Kubota SSV75** is in **good condition**, with all systems functioning as intended. With only 437 hours of operation, the machine shows minimal wear and has been well-maintained. It is ready for use in a wide range of applications without requiring immediate repairs or major maintenance.