



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2018 New Holland C232

Make & Model: 2018 New Holland C232

Machine Hours: 31



1. Exterior Condition

- **Cab Structure:** EROPS shows no signs of dents, cracks, or structural damage.
- **Paint and Decals:** Minor cosmetic scratches; decals are intact and legible.
- **Loader Arms:** No visible cracks, bends, or excessive wear.
- **Quick Attach Mechanism:** Hydraulic quick attach operates smoothly and shows no signs of leaks or damage.
- **General Cleanliness:** Exterior and cab are clean, with minimal dirt or debris accumulation.

2. Engine and Powertrain

- **Engine Performance:** Smooth start-up and operation with no unusual noises, smoke, or vibrations.
- **Fluids:** Engine oil level and condition within specifications.
- **Cooling System:** Radiator is clean and free of obstructions; coolant level is correct.
- **Belts and Hoses:** Belts are properly tensioned with no signs of cracks or wear; hoses show no leaks or damage.
- **Exhaust System:** Exhaust is secure and emits no excessive smoke.

3. Hydraulic System

- **Hydraulic Pump:** Operating efficiently with no abnormal sounds.
- **Hydraulic Fluid Levels:** Proper level and free of contamination.
- **Hydraulic Lines and Fittings:** Inspected for leaks, cracks, and abrasions – all components in excellent condition.

- **Auxiliary Hydraulics:** Ports and couplers are clean, operational, and free from leaks.

4. Tracks and Undercarriage

- **Rubber Tracks:** Tracks are new, with 100% tread remaining; no visible cracks or cuts.
- **Idlers and Rollers:** Properly aligned and free of damage.
- **Track Tension:** Correct tension observed.

5. Operator Controls and Interior

- **Cab Interior:** Clean and free of debris.
- **Seat and Restraints:** Seat is in excellent condition with functional safety restraints.
- **Controls:** All controls (joysticks, pedals) are responsive and operate as intended.
- **Gauges and Displays:** Fully functional with accurate readings.
- **Climate Control:** Heating and cooling systems operate efficiently.

6. Electrical System

- **Battery:** Securely mounted; terminals are clean and free of corrosion.
- **Lights and Indicators:** All lights (work, hazard, and interior) function properly.
- **Electrical Connections:** Inspected for corrosion or loose connections – no issues found.

7. Bucket and Attachments

- **General-Purpose Bucket:** Bucket shows no signs of excessive wear, cracks, or deformation.
- **Attachment Pins and Bushings:** Secure and free from excessive play.

8. Operational Test

- **Lifting and Lowering:** Loader arms operate smoothly without jerking or hesitation.
- **Bucket Tilt and Rollback:** Functions correctly and holds position under load.
- **Travel Performance:** Tracks propel smoothly in forward, reverse, and turning.
- **Brakes:** Responsive and hold the machine securely on inclines.
- **Hydraulic Quick Attach:** Operates as intended, allowing easy attachment changes.

Overall Condition and Notes

The 2018 New Holland C232 skid steer with only 31 machine hours is in **excellent condition**, showing minimal wear due to low usage. All systems and components inspected are fully functional, with no signs of mechanical or hydraulic issues. This machine is work-ready and suitable for immediate deployment.