



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2019 DEERE 314G

Condition: Good
Machine Hours: 33.8 Hours



Loader Arm and Boom Assembly

- Loader arms show no signs of bending, cracks, or excessive wear.
- Pivot points and bushings inspected-minimal play within manufacturer's specifications.
- Hydraulic cylinders in good condition-no visible leaks or pitting.
- Bucket linkage intact and securely fastened.

Hydraulic System

- Hydraulic fluid levels within recommended range.
- No hydraulic leaks detected at hoses, couplings, or fittings.
- Auxiliary hydraulics functioning properly-smooth operation with no loss of pressure.

Engine Compartment

- Engine starts smoothly with no unusual noises or vibrations.
- Clean and dry engine bay-no visible fluid leaks.
- Air filter inspected and clean.
- Coolant and oil levels checked and within acceptable range.

Tires

- All tires exhibit uniform wear with no cuts, cracks, or sidewall damage.
- Tread depth remains at 85% or better.
- Tire pressure verified and within manufacturer's specifications.

Operator Controls and Cab

- Hand and foot controls tested-responsive with no defects or stiffness.
- Seat and restraints in good condition with no damage.
- Gauges and indicators functioning properly.
- Cabin interior clean and free of obstructions.

Electrical System

- All lights operational (work lights, safety beacon, etc.).
- Battery terminals secure with no corrosion.
- Wiring inspected-no exposed or damaged sections found.

Chassis and Frame

- Structural integrity intact-no cracks, bends, or weld repairs detected.
- Underbody inspected for signs of damage or wear-none found.

General Operation

- Machine operates smoothly during forward and reverse travel.
- Brakes responsive and effective under load.
- Noise levels normal during operation.
- Parking brake engages securely.

Auxiliary Systems

- Auxiliary hydraulics deliver consistent power.
- Quick coupler inspected-locks and releases attachments without issue.
- Bucket and lifting arms articulate smoothly without hesitation.

Inspection Summary

The 2019 DEERE 314G Skidsteer has been thoroughly inspected and is in **good condition**. All critical systems, including the loader arm assembly, hydraulic system, engine, and tires, are functioning as intended with no major issues identified. Minor wear is consistent with machine hours and does not impact operational performance. This skidsteer is ready for immediate use.