



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2019 DEERE 317G

Equipment Details:

Model: 2019 DEERE 317G

Hours: 162

Condition: Good

Specifications:

- Enclosed ROPS (EROPS)
- Heat & Air Conditioning
- SJC Controls
- Auxiliary Hydraulics
- Rear Weight Kit
- 61 HP Yanmar Diesel Engine
- New 72" Heavy Duty Bucket
- SSL Quick Attach
- 13" Rubber Tracks
- 2,125 lbs Lift Capacity
- 8,195 lbs Operating Weight



1. Loader Arms and Attachment System

- Structural Integrity: No signs of bending, cracks, or excessive wear.
- Bucket Condition: New 72" heavy-duty bucket in pristine condition, no visible dents or wear.
- SSL Quick Attach Mechanism: Fully functional, secure locking mechanism with no alignment issues.

2. Hydraulic System

- Hoses and Fittings: Inspected for wear, cracks, and leaks; all components are in excellent condition with no issues detected.
- Auxiliary Hydraulics: Verified pressure and flow; system operates within manufacturer

specifications.

- Hydraulic Fluid Levels: Checked and topped up; fluid is clean and within recommended range.

3. Tracks and Undercarriage

- Track Condition: 13" rubber tracks exhibit uniform wear with 90% tread remaining.
- Track Tension: Properly adjusted; no sagging or misalignment noted.
- Undercarriage Components: Inspected rollers, sprockets, and idlers; all in good condition with no excessive wear.

4. Engine and Powertrain

- Engine Performance: 61 HP Yanmar diesel engine runs smoothly with no unusual noises, smoke, or vibrations.
- Oil Levels and Quality: Checked engine oil; clean and at optimal levels.
- Cooling System: Radiator and coolant levels verified; no leaks or overheating issues.
- Air Filter: Clean and free of debris.

5. Operator Controls and Cabin

- SJC Controls: Responsive and calibrated; no lag or malfunction.
- Cabin Condition: EROPS cabin is clean and free of damage. Heat and air conditioning systems are fully operational.
- Visibility: Glass panels and mirrors are intact, with no cracks or visibility obstructions.
- Instrumentation: All gauges, lights, and indicators function as intended.

6. Electrical System

- Battery and Cables: Securely mounted with no corrosion or loose connections.
- Lights: All operational, including front, rear, and safety lights.
- Wiring: Inspected for wear or damage; no issues found.

7. Overall Performance

- Lift Capacity Test: Successfully lifted 2,125 lbs to full height without issues.
- Travel Test: Smooth operation in forward and reverse; no unusual noises or vibrations.
- Braking System: Effective and responsive with no lag.

Inspection Summary

The 2019 DEERE 317G is in good condition and fully operational. With only 162 hours of use, the equipment shows minimal wear and has been well-maintained. The new 72" bucket and 90% track life enhance its overall usability and value. All systems, including hydraulics, engine, and operator controls, are functional and meet manufacturer specifications.

Inspector Notes

This Skidsteer is a work-ready machine, suitable for immediate deployment. Buyers can expect reliable performance with no significant issues identified during inspection. Maintenance records and additional details are available upon request.