



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2019 DEERE 330G



- **Model:** 2019 DEERE 330G
- **Machine Hours:** 1,201
- **Condition:** Good

1. Exterior Condition

- **Loader Arms:**
 - Checked for signs of bending, cracks, or excessive wear: **No issues found.**
- **Cab Exterior:**
 - Inspected for dents, rust, or structural damage: **Minor cosmetic scratches, no structural concerns.**
- **Paintwork:**
 - Evaluated paint condition: **Good, with minor wear consistent with age and use.**
- **Glass and Mirrors:**
 - Checked for cracks, chips, or missing components: **All glass intact and clear.**

2. Engine and Performance

- **Engine Operation:**
 - Started smoothly and ran without unusual noises or vibrations: **No issues detected.**
- **Engine Compartment:**
 - Inspected for leaks, wear, and cleanliness: **Clean and dry, no leaks present.**
- **Air Filter:**
 - Checked for cleanliness and condition: **Clean and functional.**

3. Hydraulic System

- **Hoses and Connections:**
 - Inspected for cracks, leaks, or wear: **All hoses in good condition with no visible leaks.**
- **Hydraulic Fluid Levels:**
 - Checked and topped off as needed: **Levels within recommended range.**
- **Cylinders:**
 - Inspected for smooth operation and seal integrity: **Cylinders operating correctly, no leaks detected.**

4. Undercarriage and Tires

- **Tires:**
 - Inspected for uniform wear and remaining tread depth: **Tires exhibit 80% tread remaining, no visible damage.**
- **Wheel Alignment:**
 - Checked for signs of misalignment or uneven wear: **No alignment issues noted.**

5. Bucket and Attachments

- **84in Dirt Bucket:**
 - Inspected for dents, cracks, and wear: **Good condition, minor edge wear consistent with use.**
- **QuickTach Mechanism:**
 - Verified operation and secure attachment: **Mechanism functions as designed.**

6. Operator Controls and Interior

- **ISO Controls:**
 - Tested responsiveness and accuracy: **All controls responsive and free of defects.**
- **Cab Interior:**
 - Inspected cleanliness, seat condition, and switches: **Clean and well-maintained.**
- **Heating and Air Conditioning:**
 - Verified functionality of climate control system: **Fully operational.**
- **Instrumentation and Gauges:**
 - Checked for accuracy and functionality: **All gauges and instruments functional.**

7. Electrical System

- **Battery:**
 - Checked terminals, connections, and charge level: **Battery in good condition, fully charged.**
- **Lighting:**
 - Inspected all external and internal lights for operation: **All lights functioning correctly.**
- **Wiring:**
 - Inspected for wear, fraying, or loose connections: **No visible issues.**

8. Additional Features

- **2-Speed Transmission:**
 - Tested for smooth shifting and functionality: **Operating smoothly, no issues detected.**
- **Ride Control System:**
 - Verified functionality under load: **System working as intended.**
- **Self-Leveling Bucket:**
 - Tested for proper operation: **Bucket levels correctly, no faults observed.**

Overall Assessment

The 2019 DEERE 330G Skidsteer has been thoroughly inspected and is determined to be in **good condition**. Minor cosmetic wear is consistent with its hours and age. All systems, including hydraulics, engine, and controls, are functioning correctly. This machine is ready for work and presents as a reliable addition for any job site.