



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2019 DEERE 330G

Model: 2019 DEERE 330G
Hours: 1,921
Condition: Good Condition



Exterior and Structural Components

- **Loader Arms:** Inspected for structural integrity; no cracks, bends, or excessive wear detected.
- **Frame and Chassis:** Solid and level stance; no evidence of rust, corrosion, or non-factory welds.
- **Paint and Body Panels:** Moderate wear consistent with machine hours; no significant damage.

Cab and Operator Controls

- **Cab Integrity:** EROPS in excellent condition; all glass panels intact with no cracks or chips.
- **Operator Seat:** Seat is clean and comfortable; no tears or damage.
- **Control Functionality:** Joysticks, levers, and pedals responsive; no sticking or lag in operation.
- **Displays and Gauges:** All operational and accurate; no warning lights observed.
- **Heating and Cooling Systems:** Functional; A/C and heater both operate effectively.

Engine and Powertrain

- **Engine Operation:** Smooth start; no unusual noises, vibrations, or excessive smoke.
- **Fluids:** Oil, coolant, and hydraulic fluid levels checked and within manufacturer's specifications; no leaks observed.

- **Belts and Hoses:** No visible cracks, fraying, or wear.
- **Battery and Electrical System:** Battery holds charge well; electrical connections secure and corrosion-free.

Hydraulic System

- **Hydraulic Hoses and Lines:** Inspected for leaks, wear, or damage; none detected.
- **Auxiliary Valves:** Fully operational; no delays or malfunctions.
- **Hydraulic Fluid:** Clean and within acceptable range.

Undercarriage and Tracks

- **Tracks:** Rubber tracks exhibit approximately 70% tread remaining; wear is even and within acceptable limits.
- **Track Alignment:** Properly aligned; no signs of slippage or uneven tension.

Attachments

- **Hydraulic Quick Attach Bucket:** Secure and operational; no signs of excessive wear or damage.
- **Auxiliary Attachments:** Ports functional and compatible with all attachments.

Safety Systems

- **Lighting and Indicators:** Headlights, work lights, and indicators functional.
- **Backup Alarm:** Fully operational and audible.
- **Fire Extinguisher:** Present and within certification date.

Performance Testing

- **Engine Power:** Adequate power delivery under load.
- **Hydraulics:** Smooth and responsive movement of arms and bucket.
- **Brakes:** Effective and consistent stopping power.
- **Steering:** Tight and precise control.

Inspection Summary

The 2019 DEERE 330G has been inspected thoroughly and is found to be in **good working condition**, with only minor wear consistent with its 1,921 hours of use. All systems, including hydraulics, engine, and operator controls, are functioning as intended. The machine is well-maintained and ready for immediate operation.