



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrosequipment.com

Inspection Checklist for 2019 JCB 270T

Model: JCB 270T
Year: 2019
Machine Hours: 1249
Condition: Good



General Appearance

- **Body Panels:** Inspected for dents, cracks, and rust – **No significant damage.**
- **Paint and Finish:** Minor cosmetic wear consistent with hours of use.
- **Decals and Labels:** Intact and legible.

Engine and Performance

- **Engine Startup:** Starts smoothly without hesitation or unusual noises.
- **Idle Operation:** Stable idle; no excessive vibration or smoke.
- **Horsepower:** Verified 74hp; performs as expected.
- **Oil Levels and Condition:** Within the recommended range; no contamination detected.
- **Cooling System:** Radiator and hoses free of leaks and blockages.

Hydraulic System

- **Hoses and Fittings:** Inspected for leaks, cracks, and wear – **No issues detected.**
- **Hydraulic Fluid Level:** At optimal level; fluid clean and free of debris.
- **Auxiliary Hydraulics:** Operates correctly; standard flow verified.
- **Quick Coupler:** Fully operational; no binding or wear.

Loader Arm and Boom

- **Structure:** Single arm, non-telescoping boom free of cracks, bends, or weld defects.
- **Pins and Bushings:** Checked for excessive play – **Minimal wear observed.**
- **Lifting Operation:** Smooth and responsive with no abnormal noises.

Bucket and Attachments

- **Bucket Size:** 7ft bucket inspected for structural integrity – **No cracks or deformations.**
- **Cutting Edge:** Slight wear; remains functional.
- **Attachment Locking Mechanism:** Fully operational.

Undercarriage and Tracks

- **Tracks:** Inspected for wear and tension – **80% tread remaining.**
- **Drive Motors:** Free of leaks; operate correctly under load.
- **Rollers and Idlers:** Checked for wear; no issues identified.

Operator Cabin

- **Controls:** Hand controls responsive and calibrated; no sticking or play.
- **Gauges and Indicators:** All functional; no error codes displayed.
- **Seat and Restraints:** Seat in good condition; seatbelt operational.
- **Visibility:** Glass and mirrors clean; no cracks or scratches impairing visibility.

Electrical System

- **Battery and Connections:** Secure and corrosion-free.
- **Lights:** All work as intended, including headlights and auxiliary lights.
- **Wiring:** Inspected for damage or wear; no issues found.

Overall Operation

- **Performance:** Starts, runs, and operates as expected.
 - **Stability:** Stable during operation; no tilting or instability detected.
 - **Brakes:** Tested and fully functional.
-

Summary of Condition

The 2019 JCB 270T Skidsteer has been thoroughly inspected and found to be in **good condition**, with all major components operating as intended. Minor wear is consistent with the machine's hours and usage. This equipment is ready for immediate use.