



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2019 JCB 270T



- **Model:** 2019 JCB 270T
- **Machine Hours:** 855
- **Condition:** Good

1. General Overview

- **Exterior Condition:** No significant dents, cracks, or rust visible on the body or loader arms. Paint is intact with minor scratches consistent with use.
- **Operator Cab:** Clean interior; seat and controls in good condition with no visible damage or excessive wear. A/C functioning properly.
- **Controls:** Switchable hand/foot controls responsive with no signs of malfunction.

2. Hydraulic System

- **Hydraulic Fluid:** Levels within manufacturer's recommended range; no leaks detected in hoses, fittings, or cylinders.
- **Hydraulic Quick Attach:** Operates smoothly with no delays; locking mechanism engages securely.
- **Loader Arms:** No bending, cracks, or signs of excessive wear; smooth and stable operation.

3. Engine & Powertrain

- **Engine Performance:** Starts easily, runs smoothly, and idles without unusual noises or vibrations.
- **Air Filters:** Clean with no signs of clogging; replaced as part of routine maintenance.
- **Cooling System:** Radiator and cooling fan free from debris; no signs of overheating during operation.
- **Exhaust System:** Properly secured with no leaks or damage.

4. Undercarriage & Tracks

- **Tracks:** Caterpillar tracks in good condition with approximately 85% tread remaining; no cracks, tears, or uneven wear.
- **Track Tension:** Correctly adjusted per manufacturer specifications.
- **Rollers & Idlers:** No excessive play or visible damage; operate quietly and smoothly.

5. Electrical System

- **Battery:** Properly secured with no corrosion on terminals; holds charge effectively.
- **Lighting:** All lights (work lights, indicators) operational with no broken lenses.
- **Instrumentation:** Dashboard gauges and displays function accurately.

6. Attachments

- **84" Bucket:** Structurally sound with no cracks or excessive wear; cutting edge intact.
- **Power Quick Attach:** Functions as intended; attachment swaps completed without issue.

7. Transmission & Drive System

- **2-Speed Transmission:** Engages correctly; no delays or unusual noises during gear shifts.
- **Drive Motors:** Operate smoothly and consistently; no leaks or performance issues detected.
- **Braking System:** Brakes responsive and effective without noise or dragging.

8. Fluids & Maintenance

- **Engine Oil:** Clean and at proper levels; recently changed as part of routine service.
- **Coolant:** Free of contaminants; level within specifications.
- **Grease Points:** All fittings properly lubricated with no evidence of neglect.

9. Safety Equipment

- **ROPS (Roll-Over Protective Structure):** No damage or modifications; meets safety standards.
- **Seat Belt:** Operates smoothly and locks securely.
- **Fire Extinguisher:** Properly mounted and charged.

Summary

The 2019 JCB 270T skid steer has been thoroughly inspected and is in **good condition**, reflecting its low machine hours (855). Minor cosmetic wear is present but does not impact functionality. All systems, including the hydraulic quick attach, 2-speed transmission, and A/C, are fully operational. The machine is ready for immediate use.