



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2019 Kubota SVL95-2S

Equipment Details:

- Make and Model: 2019 Kubota SVL95-2S
- Machine Hours: 962
- Condition: Good



Loader Arms and Attachments

- Loader arms inspected for cracks, bends, or deformation. No structural issues found.
- Hydraulic Quick Attach operates smoothly, locks and unlocks attachments securely.
- 4N1 Bucket inspected for dents, wear, and weld integrity. Minor cosmetic wear consistent with hours of use; fully functional.

Hydraulic System

- Hydraulic fluid levels within recommended range.
- Hydraulic hoses inspected for leaks, wear, and cracks. No issues detected.
- Auxiliary valves tested for responsiveness and pressure. All valves operational and performing as expected.

Engine and Performance

- Engine start-up smooth and responsive with no unusual noises or vibrations.
- Engine operation: No visible smoke or signs of excessive wear.

- Oil levels and quality checked and within specifications; no contamination found.

Cab and Operator Controls

- Cab environment (EROPS) clean and well-maintained; heat and A/C functional.
- Operator controls responsive and free of defects or delays.
- Seat in good condition with no tears; clear visibility through all glass.

Tracks and Undercarriage

- Rubber tracks tread wear at approximately 85%; even wear with no visible cracks.
- Track tension checked and adjusted to specifications.
- Undercarriage components inspected for wear and damage. All rollers and idlers in good condition.

Electrical System

- Lights operational for front and rear.
- Battery terminals clean and secured; charge within acceptable range.
- Instrument panel fully functional, with no error codes displayed.

Safety Features

- Backup alarm fully operational.
- Seatbelt checked and in good working condition.
- Emergency exits confirmed clear and functional.

General Condition

- Exterior body panels: Minor scratches consistent with hours of use; no significant damage.
- Paint and decals intact, with minor wear visible.
- Fluid leaks: None detected in engine, hydraulic, or cooling systems.

Overall Assessment:

The 2019 Kubota SVL95-2S is in good condition, consistent with the recorded 962 hours of use. Minor cosmetic wear does not affect performance or safety. The machine is work-ready, with all systems fully operational and requiring no immediate repairs or maintenance.