



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2019 New Holland C245

- **Make and Model:** 2019 New Holland C245
- **Machine Hours:** 134



Exterior and Structural Components:

1. **Loader Arms:** Inspected for bending, cracks, or excessive wear — **No issues found.**
2. **Cab Exterior:** Paint intact, no dents or damage — **Excellent condition.**
3. **Safety Decals and Labels:** Present and legible — **Compliant.**
4. **Hydraulic Quick Attach:** Operates smoothly, no visible leaks or damage — **Fully functional.**

Cab and Operator Controls:

1. **Cab Interior:**
 - Seat and controls free of damage — **Like new.**
 - HVAC system operational, AC blows cold, and heater functions as expected — **Verified.**
2. **Operator Controls:**
 - Pilot controls are responsive and precise — **Fully functional.**
 - Switches, dials, and electronic displays are operational — **Verified.**
3. **Visibility:**
 - Glass panels and mirrors intact and clean — **Excellent condition.**

Hydraulic System:

1. **Hydraulic Pump and Lines:**
 - No leaks or wear on hoses and fittings — **Excellent condition.**
2. **Auxiliary Hydraulics:**
 - High Flow system operates within specifications — **Fully functional.**

3. **Cylinders:**
 - No dents, scoring, or leaks — **Excellent condition.**

Engine and Powertrain:

1. **Engine:**
 - Starts off the key every time — **Verified.**
 - Runs smoothly with no unusual noises or vibrations — **Stout and reliable.**
 - Fluids (oil, coolant) checked and at proper levels — **Verified.**
2. **Transmission:**
 - Two-speed functionality tested — **Shifts smoothly.**
3. **Battery:**
 - Terminals clean and connections secure — **Tested and functional.**

Tracks and Undercarriage:

1. **Tracks:**
 - Rubber tracks show minimal wear — **Excellent condition.**
 - Tread depth consistent and near new specifications — **Verified.**
2. **Undercarriage Components:**
 - Rollers, idlers, and sprockets inspected for wear — **No issues found.**

Performance Test:

1. **Drivability:**
 - Drives like new with no pulling or vibrations — **Verified.**
2. **Lifting and Tilting:**
 - Loader arms operate smoothly under load — **Fully functional.**
3. **Brakes:**
 - Parking and service brakes responsive — **Tested and operational.**

Lighting and Electrical Systems:

1. **Lights:**
 - Work lights, hazard lights, and indicators functional — **All verified.**
2. **Electrical System:**
 - Wiring inspected for damage or wear — **No issues found.**

Maintenance and Fluids:

1. **Oil and Filters:**
 - Engine oil and filter recently replaced — **Good condition.**
2. **Hydraulic Fluid:**
 - Checked and at proper levels with no contamination — **Verified.**
3. **Coolant and Fuel:**

- Coolant at appropriate levels, no leaks observed — **Verified.**
 - Fuel system inspected for leaks or obstructions — **Good condition.**
-

Overall Assessment:

The 2019 New Holland C245 is in **exceptional condition**, as described. With only 134 original hours, the machine operates like new. All systems, including the hydraulic quick attach, high-flow auxiliary hydraulics, and HVAC, function flawlessly. This machine is ready for immediate use with no additional maintenance required.