



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2019 BOBCAT S740

- **Model:** 2019 BOBCAT S740
- **Machine Hours:** 404
- **Condition:** Good



1. General Condition

- **Visual Inspection:** No major dents, scratches, or structural damage.
- **Paint:** Minor cosmetic wear, but overall well-maintained finish.

2. Loader Arms & Hydraulic System

- **Loader Arms:** No signs of bending, cracks, or excessive wear.
- **Hydraulic Cylinders:** Inspected for leaks and wear; no issues found.
- **Hydraulic Hoses:** Checked for cracks, leaks, or bulging; all hoses in good condition.
- **Hydraulic Fluid:** Levels within recommended range, clean, and free of contamination.

3. Tires

- **Condition:** 12x16.5 tires show 85% tread remaining with uniform wear.
- **Pressure:** Verified and within manufacturer's specifications.

4. Engine & Cooling System

- **Engine:** 74 HP Doosan Diesel Engine operates smoothly with no unusual noises or vibrations.
- **Oil Levels:** Checked and at appropriate levels; oil appears clean.
- **Reversing Fan:** Fully operational, ensuring proper cooling performance.
- **Air Filters:** Clean and free from debris.

5. Auxiliary Hydraulics

- **Hydraulic Connections:** All auxiliary ports tested and fully functional.
- **Flow Performance:** Adequate flow rate observed; no performance issues detected.

6. Operator Controls & Cab

- **SJC Controls:** Responsive and free of defects.
- **Cab Interior:** Clean and intact; no damage to panels or upholstery.
- **Visibility:** Glass panels clean and free from cracks.
- **Heating & Air Conditioning:** Both systems tested and functioning correctly.
- **Safety Features:** Horn, seatbelt, and backup alarm operational.

7. Attachments

- **72" General Purpose Bucket:** Checked for structural integrity; no cracks, bends, or excessive wear.
- **Quick Attach System:** Hydraulic SSL Quick Attach mechanism operates smoothly and securely locks attachments in place.

8. Electrical Systems

- **Battery:** Voltage tested; no issues with starting.
- **Lighting:** All exterior and interior lights operational.
- **Control Panel:** All indicators and gauges functioning properly.

9. Undercarriage & Frame

- **Frame:** Inspected for structural integrity; no signs of damage or stress.
- **Undercarriage:** Free from excessive dirt or debris; no visible damage.

10. Operational Test

- **Lift & Tilt:** Loader arms and tilt function smooth under load.
 - **Steering:** Precise and responsive during maneuvers.
 - **Braking:** Effective and reliable.
 - **Noise Levels:** Normal operational noise observed; no unusual sounds during operation.
-

Inspection Summary

The 2019 BOBCAT S740 is in **good condition**, with minor cosmetic wear consistent with its 404 hours of operation. All key systems, including the engine, hydraulics, and controls, have been thoroughly inspected and are fully functional. This skidsteer is work-ready and well-maintained.

-