



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2019 BOBCAT T595

Skidsteer Equipment Details

Model: 2019 BOBCAT T595

Machine Hours: 2040

Condition: Good

Specifications:

- Enclosed ROPS (EROPS)
- Heat & Air
- SJC Controls
- AUX Hydraulics
- A71 Package
- Rear Weight Kit
- 74 HP Doosan Diesel Engine
- 74" Tooth Bucket
- Hydraulic SSL Quick Attach
- 18" Rubber Tracks
- 2,199 lbs Lift Capacity
- 8,055 lbs Operating Weight



Cab and Operator Controls

- **Cab Structure:** EROPS inspected; no visible damage, cracks, or rust. Excellent overall condition.
- **Climate Control:** Heat and air conditioning operational; blower and vents working as intended.
- **Operator Controls:** SJC controls are responsive and free from defects or excessive wear.
- **Instrumentation:** Gauges, lights, and indicators function properly without error codes.
- **Seat and Interior:** Seat is clean, well-secured, and free of tears or significant wear. Cab interior is clean and intact.

Hydraulic System

- **Hydraulic Hoses:** Inspected for cracks, leaks, and abrasions; all hoses in good condition.
- **Auxiliary Hydraulics:** Auxiliary hydraulic functions tested; no leaks and operate smoothly.
- **Hydraulic Fluid Levels:** Checked and topped off; within manufacturer specifications.
- **Hydraulic Coupler:** Hydraulic SSL quick attach functions as intended without sticking or abnormal resistance.

Engine and Powertrain

- **Engine Performance:** 74 HP Doosan diesel engine runs smoothly with no unusual noises or vibrations.
- **Fluids and Filters:** Oil, coolant, and fuel levels are within recommended ranges; filters inspected and replaced as needed.
- **Belts and Hoses:** Engine belts and hoses are intact, free from cracks, and properly tensioned.
- **Exhaust System:** No excessive smoke or unusual emissions; compliant with operational standards.

Loader Arms and Mechanisms

- **Loader Arms:** No signs of bending, cracking, or excessive wear; all joints and pins well-lubricated.
- **Bucket Mount:** 74" tooth bucket securely attached; no visible damage to mounting points.
- **Hydraulic Lift:** Hydraulic lift cylinders operate smoothly and hold positions without drift.
- **Lift Capacity:** Verified operational capacity at 2,199 lbs; no issues under maximum load.

Undercarriage and Tracks

- **Rubber Tracks:** 18" tracks exhibit uniform wear with 70% tread life remaining.
- **Track Tension:** Adjusted to manufacturer specifications; no slippage or misalignment.
- **Undercarriage Components:** Rollers, sprockets, and idlers inspected; all in good condition with no excessive wear.

Electrical System

- **Battery and Connections:** Battery terminals clean and secure; voltage tested within range.

- **Lighting:** Front and rear lights operational; no damaged or missing bulbs.
- **Safety Features:** Backup alarm and safety interlocks functioning as intended.

General Condition

- **Paint and Body:** Minimal scratches consistent with normal use; no significant dents or rust.
- **Rear Weight Kit:** Properly installed and secure; no defects.
- **Overall Cleanliness:** Machine cleaned and free of debris inside and out.

Test Operation

- **Driving Test:** Smooth travel in all directions; no abnormal noises or resistance.
- **Two-Speed Travel:** Functioned properly during operation.
- **Hydraulic Functions:** Loader, bucket, and auxiliary functions performed without hesitation or issue.

Inspection Summary

The 2019 BOBCAT T595 is in **good operational condition** and ready for work. All key components and systems have been inspected and are functioning within manufacturer specifications. Minor cosmetic wear is present but does not affect performance. This machine represents a reliable and well-maintained Skidsteer.