



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2019 BOBCAT T750



Equipment Model: 2019 BOBCAT T750

Machine Hours: 894 Hours

Condition: Good

Structural Integrity

- Loader Arms: Inspected for bending, cracks, or excessive wear—no issues found. Loader arms in good condition.
- Quick Attach System: Operates smoothly, locking mechanism secure and free of damage.
- Chassis and Frame: No cracks, welds, or structural deformities detected.

Hydraulic System

- Hydraulic Hoses: Checked for leaks, wear, or damage—all hoses in good condition.
- Hydraulic Fluid Levels: Verified fluid is within recommended range, no contamination observed.
- Auxiliary Hydraulics: Function tested; pressure and flow rates are within specifications.

Powertrain

- Engine: Smooth operation with no unusual noises or vibrations. Oil and coolant levels within normal range.
- Cooling System: Radiator and cooling fans inspected; no leaks or obstructions.

- Transmission: Verified smooth shifting; no performance issues detected.

Operator Controls

- Joystick Controls: Responsive and free of defects.
- Pedals and Levers: Inspected for wear; all functioning as intended.
- Safety Switches: Tested; operational and in good condition.

Undercarriage

- Tracks: Rubber tracks exhibit uniform wear; tread life estimated at 75% remaining.
- Rollers and Sprockets: Inspected for wear and alignment; no issues detected.
- Frame: Level stance; no signs of twisting or misalignment.

Electrical System

- Battery: Terminals clean and secure; charge level sufficient.
- Lighting: All lights operational, including work lights.
- Wiring: No visible fraying, corrosion, or loose connections.

Attachments

- Bucket: Quick Attach Bucket inspected; cutting edge in good condition with no cracks or excessive wear.
- Mounting Points: Secure and free of damage or deformation.

Operator Station

- OROPS (Open Roll Over Protection System): Frame inspected; no damage or bending observed.
- Seat and Controls: Operator seat intact and adjustable; all controls functional.
- Visibility: Operator's field of view unobstructed.

Performance Tests

- Engine Start-Up: Starts smoothly with no delays or unusual emissions.
- Hydraulic Operation: Loader arms and bucket operate without hesitation or strain.
- Travel and Steering: Tracks respond to controls; no pulling or lag detected.

Maintenance

- Filters and Fluids: Air, fuel, and oil filters in good condition; recent servicing noted.
- Lubrication Points: All greased appropriately; no dry fittings found.

FINAL CONDITION SUMMARY

This 2019 BOBCAT T750 is in Good Condition, showing normal wear for its 894 operating hours. The machine is fully operational with no significant defects or repairs needed. Routine maintenance has been performed, and all systems have been verified to meet operational standards. The Skidsteer is ready for immediate use.