



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2019 John Deere 332G

Equipment Details

Model: 2019 DEERE 332G

Hours: 1,144

Condition: Good (Very good overall condition)



Inspection Summary

This inspection was conducted to ensure the 2019 DEERE 332G Skidsteer meets operational and safety standards. Below is a comprehensive checklist of all components inspected by our professional mechanic, along with their respective findings.

Inspection Checklist

Structural Components

- Loader Arms: Inspected for cracks, bends, or excessive wear—no structural issues detected.
- Boom Pins and Bushings: Checked for wear and movement—minor wear within normal operating limits.
- Chassis: Inspected for damage or deformations—frame is solid and shows no defects.

Hydraulic System

- Hydraulic Hoses: No visible leaks or wear; connections are secure.
- Hydraulic Fluid: Fluid level within recommended range; fluid appears clean.
- Hydraulic Cylinders: Inspected for leaks and damage—none detected.

Engine

- Engine Operation: Starts smoothly, runs without unusual noises, vibrations, or smoke.
- Oil Level and Quality: Checked and verified; oil appears clean with no contaminants.
- Belts and Hoses: All in good condition with no cracks or wear.
- Air Filter: Clean and free of debris.

Transmission

- Drive System: Checked for smooth operation and responsiveness—no issues detected.
- Fluid Levels: Verified and within acceptable range.

Operator's Cabin

- Controls: All controls are responsive and function as intended.
- Seat and Restraints: Seat is in excellent condition; seatbelt functional.
- Display Panel: Gauges and warning lights operational.
- Visibility: Windows clean and free of cracks or damage.
- Comfort Features: Heat and air conditioning systems operational.

Tracks and Undercarriage

- Rubber Tracks: Uniform wear with approximately 85% tread life remaining.
- Track Tension: Properly adjusted; no sagging or over-tightness.
- Rollers and Idlers: Inspected for wear; all components in good condition.

Electrical System

- Battery: Fully charged; terminals clean and connections secure.
- Lighting: All lights (work lights, indicators) operational.
- Safety Alarms: Backup alarm and horn functional.

Auxiliary Systems

- Auxiliary Hydraulics: Verified flow and pressure; system operates as intended.
- Quick Attach Coupler: Inspected for wear and proper operation—no issues detected.

General Condition

- Exterior Appearance: Paint in very good condition with minimal scratches or wear.
- Fluids: All fluid levels checked and within specifications; no leaks detected.

- Cleanliness: Equipment cleaned and detailed; ready for operation.

Overall Assessment

The 2019 DEERE 332G Skidsteer is in very good condition with minimal wear consistent with 1,144 hours of operation. All systems have been inspected and are operational without any major issues or safety concerns. This machine is work-ready and meets industry standards.