

Albatross Equipment Earthworks 10998 WY-789 Riverton, WY 82501 www.albatrosequipment.com

Inspection Checklist for 2020 DEERE 331G



Cab and Operator Controls

- [x] Enclosed ROPS/Cab: Inspected for structural integrity; no cracks or visible damage.
- [x] Air Conditioning System: Fully operational; no leaks or unusual noises detected.
- [x] Keyless Start: Verified functionality; starts smoothly without delay.

- [x] Operator Seat and Controls: No tears or damage; controls are responsive and free of defects.

- [x] Cab Glass and Doors: No cracks, chips, or obstructions; all seals intact.

Engine and Powertrain

- [x] Engine Performance: Runs smoothly with no unusual noises, vibrations, or smoke.

- [x] Fluid Levels: Engine oil, coolant, and hydraulic fluid levels are within recommended ranges.

- [x] Belts and Hoses: Inspected for wear or cracks; all components are secure and in good condition.

- [x] Two-Speed Transmission: Engages seamlessly; no issues observed during operation.

Hydraulic System

- [x] Auxiliary Hydraulics: Fully operational; tested with attachments, no leaks detected.

- [x] Hydraulic Hoses and Cylinders: Inspected for wear, leaks, or damage; all components in good condition.

- [x] High Flow System: Confirmed operational; adequate flow rate for heavy-duty applications.

Loader Arms and Attachments

- [x] Loader Arms: Inspected for bending, cracks, or excessive wear; structural integrity confirmed.

- [x] 80" Bucket: Checked for wear, cracks, and weld integrity; cutting edge is in good condition.

- [x] Quick Attach System: Engages and disengages smoothly; locking mechanisms are functional.

Tracks and Undercarriage

- [x] Rubber Tracks: Brand new tracks installed; no wear or damage.

- [x] Rollers and Idlers: Inspected for proper alignment and smooth operation.

- [x] Track Tension: Adjusted to manufacturer's specifications.

Electrical System

- [x] Lights: All exterior and interior lights tested; fully operational.

- [x] Battery and Connections: Battery is fully charged; terminals clean and securely connected.

- [x] Warning Indicators: No error codes or warning lights active during operation.

General Condition

- [x] Exterior Panels and Paint: Checked for dents, scratches, and rust; minor cosmetic wear consistent with use.

- [x] Chassis and Frame: Level and free of any structural damage or signs of fatigue.

- [x] Safety Features: Seatbelt, horn, and backup alarm fully functional.

Inspection Summary

The 2020 DEERE 331G Skidsteer is in **good condition** and is ready for work. All critical systems, including the hydraulic, engine, and track systems, were inspected and found to be in excellent working order. The brand-new rubber tracks enhance operational reliability. Minor cosmetic wear was observed on exterior panels, but it does not impact performance

or structural integrity. This machine is a dependable and well-maintained piece of equipment, suitable for a variety of tasks.