



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2020 DEERE 333G

Model: 2020 DEERE 333G
Machine Hours: 1,059
Condition: Good



General Overview

- **Visual Condition:** Machine exterior shows normal wear consistent with hours. No significant dents, scratches, or corrosion observed.
- **Cleanliness:** Equipment cleaned and free of excess dirt or debris.

Tracks

- **Track Width:** 18-inch tracks inspected for wear.
- **Tread Depth:** 85% tread remaining; no visible cracks or uneven wear.
- **Track Tension:** Correct tension observed; no adjustments required.

Engine

- **Oil Level and Quality:** Engine oil is at the recommended level, and quality is good with no signs of contamination.
- **Startup and Operation:** Engine starts smoothly with push-button start; no unusual noises, vibrations, or smoke detected.
- **Air Filter:** Inspected and in good condition; replacement not necessary.
- **Cooling System:** Radiator and cooling components free of leaks or blockages; coolant level within specification.

Hydraulic System

- **Fluid Levels:** Hydraulic fluid is at optimal level and free of contaminants.
- **Hoses and Fittings:** No leaks, cracks, or excessive wear detected on hydraulic hoses or fittings.
- **Performance:** Hydraulics operate smoothly and with full power.

Loader Arm and Quick Attach

- **Structural Integrity:** Loader arms inspected for cracks, bends, or other deformations; none observed.
- **Quick Attach System:** Hands-free quick attach mechanism functions properly, locks securely, and shows no signs of damage.

Cab and Operator Controls

- **Cab Condition:** Fully enclosed cab is clean and in good condition. No cracked windows or doors.
- **Climate Control:** Heat and air conditioning function as intended.
- **Operator Controls:** Hand controls, foot throttle, and dial throttle are responsive and operational.
- **Electronics:** Radio, electronic display, and backup camera are fully functional.

Electrical System

- **Battery:** Battery voltage within normal range; terminals clean and secure.
- **Lighting:** All exterior and interior lights operational with no signs of dimming or flickering.

Performance Test

- **Travel and Steering:** Machine travels smoothly in both directions with precise steering.
- **Braking:** Brakes are responsive and effective.
- **Self-Leveling:** Self-leveling feature functions correctly.

Fluid Leakage

- **Inspection Areas:** Inspected undercarriage, hydraulic hoses, and engine bay for leaks.
- **Result:** No fluid leaks detected.

Final Assessment

The 2020 DEERE 333G Skid Steer is in **good overall condition**, with all systems functioning as intended. Tracks show minimal wear, hydraulics operate efficiently, and the cab is clean and well-maintained. This machine is ready for immediate use.