



**Albatross Equipment Earthworks**  
10998 WY-789 Riverton, WY 82501  
[www.albatrossequipment.com](http://www.albatrossequipment.com)

## Inspection Checklist for 2020 TAKEUCHI TL8

- **Make & Model:** 2020 Takeuchi TL8
- **Machine Hours:** 1,064
- **Condition:** Good



### Inspection Checklist

#### General Condition

- **Exterior Appearance:** Paint is intact, with minor cosmetic scratches from normal use. No significant dents or damage.
- **Decals & Labels:** Clear and legible, with minimal fading.
- **Safety Features:** All safety decals and operational warnings are in place.

#### Loader Arms & Bucket

- **Loader Arm Condition:** Structural integrity verified, no cracks or deformations detected.
- **Hydraulic Quick Attach:** Operates smoothly, locks securely. No excessive wear or damage.
- **Bucket Condition:** Minimal wear, cutting edge intact and free from excessive damage.

#### Hydraulic System

- **Hydraulic Fluid Level:** Within recommended range. No leaks detected.
- **Hydraulic Hoses & Fittings:** Inspected for wear, cracks, and leaks. All fittings are secure.
- **Auxiliary Hydraulics:** Tested and functioning properly.

#### Tracks and Undercarriage

- **Rubber Track Condition:** Approximately 85% tread remaining. No cuts, tears, or significant damage.
- **Track Tension:** Correctly adjusted to manufacturer specifications.
- **Rollers & Idlers:** Checked for wear and alignment. Operate smoothly without unusual noises.

## Engine

- **Engine Oil Level:** Within range, clean with no signs of contamination.
- **Engine Operation:** Starts smoothly, idles consistently, and accelerates without hesitation.
- **Unusual Noises or Vibrations:** None detected during operation.

## Cooling System

- **Coolant Level:** Within recommended levels.
- **Radiator & Hoses:** No leaks, cracks, or blockages.
- **Fan Operation:** Functions properly without abnormal noises.

## Cabin & Controls

- **EROPS:** Enclosure seals properly, with no visible damage or wear.
- **Controls:** Fully functional, responsive, and free from defects.
- **Seat & Safety Features:** Seat in good condition, safety belts operational.
- **Visibility:** Windows and mirrors are clean and free of cracks.

## Electrical System

- **Battery:** Holds charge, terminals clean and secure.
- **Lighting:** All lights operational (headlights, tail lights, and indicators).
- **Gauges & Monitors:** All dashboard indicators functional.

## Operational Test

- **Drive System:** Smooth operation in forward and reverse. No jerking or slipping.
  - **Braking System:** Fully functional with no abnormal resistance or noise.
  - **Steering:** Responsive and smooth during operation.
- 

## Inspection Summary

The 2020 Takeuchi TL8 Skidsteer is in **good condition**, showing normal wear consistent with its 1,064 operating hours. The equipment has been thoroughly inspected and is ready for operation without requiring immediate maintenance.