



**Albatross Equipment Earthworks**  
10998 WY-789 Riverton, WY 82501  
[www.albatrossequipment.com](http://www.albatrossequipment.com)

## Inspection Checklist for 2020 Kubota SVL65-2



- Make and Model: 2020 Kubota SVL65-2
- Machine Hours: 1,476
- Condition: Good

### Exterior and Structural Integrity

- Loader arms inspected for cracks, bending, or excessive wear—no issues found.
- Exterior panels and EROPS (enclosed ROPS) cabin show no dents, cracks, or damage.
- Paint in good condition with minor scratches consistent with regular use.
- Frame and undercarriage inspected for integrity and alignment—no deformation noted.

### Hydraulic System

- Hydraulic hoses checked for leaks, wear, or cracks—no visible issues.
- Hydraulic fluid levels within the recommended range.
- Auxiliary hydraulic valves operational with no performance issues.
- Hydraulic quick-attach bucket system tested and functioning correctly.

### Tracks and Undercarriage

- Rubber tracks show uniform wear with approximately 80% tread remaining.
- Track tension checked and adjusted as necessary.
- Undercarriage components, including rollers and sprockets, inspected for wear—all in good condition.

### **Engine and Powertrain**

- Engine starts smoothly with no unusual noises, smoke, or vibrations.
- Engine oil level and condition verified—fresh service completed.
- Fuel system checked for leaks or blockages—none detected.
- Cooling system inspected; radiator clean and coolant levels optimal.

### **Electrical System**

- Battery terminals clean and secure; voltage output verified within specifications.
- Lights (headlights and work lights) tested and operational.
- Instrument panel and gauges responsive with no error codes displayed.

### **Operator Controls and Cabin**

- Joystick and foot pedal controls responsive with no sticking or excessive play.
- Operator seat clean, functional, and free of tears.
- Visibility from the cab unobstructed with intact glass and functional wipers.

### **Attachments and Additional Features**

- Quick-attach bucket locks securely in place.
- Bucket inspected for wear and dents—minor cosmetic scratches noted, no functional issues.
- Auxiliary valve flow tested and fully operational.

### **Maintenance and Fluids**

- All fluids topped off, including engine oil, hydraulic fluid, and coolant.
- Service intervals checked and adhered to—next service recommended at 1,600 hours.
- Filters (air, oil, hydraulic) inspected and replaced as needed.

### **Final Assessment**

- Overall condition: Good
- Machine is work-ready with no significant issues.
- Recommended minor cosmetic touch-ups for scratches if desired.

### **Summary**

The 2020 Kubota SVL65-2 has been thoroughly inspected and is deemed to be in good working condition. All systems are operational, and the machine is ready for immediate use.

Regular maintenance has been performed, and no significant repairs are required at this time.