



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2020 Kubota SVL65-2



- **Model:** Kubota SVL65-2
- **Year:** 2020
- **Hours:** 754

Exterior Condition

- **Cab/EROPS:**
 - Inspected enclosed cab—glass is intact with no cracks or scratches.
 - Doors open and close properly; seals are intact and provide adequate insulation.
- **Paint and Body Panels:**
 - Paint shows minimal wear with minor surface scratches consistent with machine hours.
 - No dents or structural damage to body panels.

Mechanical Systems

- **Engine:**
 - Kubota 68 HP diesel engine runs smoothly with no unusual noises or vibrations.
 - Engine oil level checked—within recommended range and recently serviced.

- No visible leaks or signs of wear around engine components.
 - **Hydraulics:**
 - Auxiliary hydraulic lines and fittings inspected—no leaks, cracks, or signs of excessive wear.
 - Hydraulic fluid level within manufacturer specifications.
 - Hydraulic quick attach system functions properly with no delays or issues.
 - **Loader Arms and Bucket:**
 - Loader arms show no signs of bending, cracking, or excessive wear.
 - 74" GP bucket inspected—edges and teeth show standard wear, but structurally sound.
 - SSL quick attach mechanism engages and disengages smoothly.
 - **Tracks:**
 - 16" rubber tracks exhibit uniform wear with approximately 85% tread life remaining.
 - Track tension adjusted within manufacturer recommendations.
 - **Transmission/Drivetrain:**
 - 2-speed transmission shifts smoothly between low and high gears.
 - Drivetrain components in good condition; no unusual noises during operation.
-

Operator Controls and Cabin

- **Controls:**
 - Pilot controls are responsive and operate without sticking or delays.
 - Joysticks, switches, and levers are free of damage and functional.
- **Electrical Systems:**
 - All lights (headlights, indicators) operational.
 - Dashboard displays clear, with no warning or error codes.
- **Comfort Features:**

- Heat and air conditioning tested—fully functional, providing adequate temperature control.
 - Radio operates correctly.
-

Performance Testing

- **Lift Capacity:**
 - Rated at 2,100 lbs—performed under normal load with no loss of power or stability.
 - **Steering and Maneuverability:**
 - Steering is smooth; no issues noted during directional changes or tight turns.
-

Summary of Condition

This 2020 Kubota SVL65-2 is in **good condition**, with only minor cosmetic wear consistent with 754 hours of use. All mechanical, hydraulic, and operator systems have been tested and are fully operational. The machine is **work-ready** with no significant repairs or maintenance required at the time of inspection.