



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2020 KUBOTA SVL95-2S

Equipment Details

- Make & Model: 2020 KUBOTA SVL95-2S
- Hours: 1,437
- Condition: Good



Comprehensive Inspection Checklist

Structural Integrity

- Loader arms inspected for cracks, bending, or excessive wear — No issues found.
- Frame and chassis inspected for structural integrity — No damage or deformation present.
- Counterweights and mounts secured and intact.

Engine and Powertrain

- Engine starts smoothly with no unusual noises, smoke, or vibrations.
- Oil level checked and within recommended range — No leaks detected.
- Air filter and housing inspected — Clean and serviceable.
- Coolant checked for proper level and condition — No contamination or leaks found.

Hydraulic System

- Hydraulic fluid levels within specification — No visible leaks or excessive wear on hoses.
- High flow and auxiliary hydraulic valves tested — Operational with no faults detected.
- Hydraulic quick attach system tested — Functions properly with no delays or malfunctions.
- Cylinders inspected for leaks and smooth operation — No issues identified.

Undercarriage and Tracks

- Rubber tracks exhibit uniform wear with at least 80% tread remaining.
- Track tension adjusted and within specification.

- Rollers and idlers inspected for smooth operation and wear — No damage or misalignment.

Bucket and Attachments

- Hydraulic quick attach bucket system inspected — Secure and operational.
- Bucket edges and welds checked for wear and cracks — No issues found.
- Tilt and lift functions tested — Responsive and smooth operation.

Operator's Cabin

- Enclosed ROPS (EROPS) structure inspected for safety compliance — No damage.
- Operator seat and controls checked — All controls responsive and seat in good condition.
- Cabin glass free of cracks or significant scratches.
- Heating and air conditioning systems tested — Fully operational.
- Dashboard and display panel inspected — All indicators and gauges functional.

Electrical Systems

- Lights and signals tested — All operational.
- Battery terminals checked for corrosion — Clean and secure.
- Wiring and connectors inspected — No visible wear or damage.

Safety Features

- Backup alarm and camera tested — Working as intended.
- Seatbelt and restraint systems inspected — No defects.
- Emergency exits and safety decals visible and intact.

Inspection Summary

The 2020 KUBOTA SVL95-2S has been thoroughly inspected and is determined to be in good condition, with no major defects or issues noted during the inspection. All systems are functional, and the machine is ready for work. Minor wear consistent with hours and usage has been observed but does not impact performance.