



**Albatross Equipment Earthworks**  
10998 WY-789 Riverton, WY 82501  
[www.albatrossequipment.com](http://www.albatrossequipment.com)

## Inspection Checklist for 2021 DEERE 325G



### Equipment Details

- Model: 2021 DEERE 325G
- Hours: 1,103
- Condition: Good Condition
- Features: Rubber track, OROPS, Quick Attach Bucket, Auxiliary Valves

### Inspection Summary

The inspection of the 2021 DEERE 325G Skidsteer has been conducted by a professional mechanic. Below is a detailed report of the equipment's condition and performance.

### Loader Arms and Attachments

- \*\*Loader Arms:\*\*** Show no signs of bending, excessive wear, or cracks.
- \*\*Quick Attach Mechanism:\*\*** Fully operational and locks attachments securely.
- \*\*Bucket Condition:\*\*** No dents, cracks, or warping; cutting edge in good condition with minimal wear.

### Hydraulic System

- \*\*Hydraulic Hoses and Lines:\*\*** No visible leaks or wear.
- \*\*Auxiliary Valves:\*\*** Functioning as intended, no loss of pressure.
- \*\*Hydraulic Fluid Levels:\*\*** Within manufacturer-recommended range.

### Tracks and Undercarriage

- \*\*Rubber Tracks:\*\*** Uniform wear with approximately 85% tread remaining. No cracks or deformations.
- \*\*Rollers and Idlers:\*\*** Roll smoothly with no excessive play or damage.
- \*\*Track Tension:\*\*** Adjusted within specifications.

### Engine and Powertrain

**Engine Condition:** Starts smoothly and operates without unusual noise, vibrations, or smoke.

**Oil Levels:** Clean and within range.

**Air Filter:** Inspected and found clean; no replacement required.

**Cooling System:** No leaks, overheating, or obstructions.

**Exhaust System:** Free of rust, leaks, or soot buildup.

### Operator Station

**ROPS Structure:** Fully intact with no structural damage.

**Seat and Controls:** Operator seat is in good condition with no tears; controls are responsive and functional.

**Instrumentation Panel:** All gauges and indicators work as designed.

### Electrical System

**Battery:** Terminals clean and secure; voltage levels normal.

**Lights and Signals:** All functioning, no burnt-out bulbs.

**Wiring:** Inspected for wear and secure connections; no issues detected.

### Hydraulic and Cooling Systems

**Cooling System Hoses:** No signs of wear or leaks.

**Radiator:** Clean, no obstructions or damage.

**Pump Performance:** Efficient, with no abnormal noises during operation.

### Safety Features

**Brakes:** Functional and responsive.

**Safety Switches:** All tested and operational.

**Backup Alarm:** Audible and working correctly.

### Overall Condition

**General Appearance:** Equipment shows normal signs of use consistent with hours and good maintenance history. Paint is intact with minor scratches.

**Maintenance Records:** Confirmed regular servicing; no overdue maintenance tasks.

### **Mechanic's Notes**

The 2021 DEERE 325G is in good condition with no significant issues. Routine maintenance is up-to-date, and the equipment is ready for work. Minor wear is consistent with its hours of operation. Rubber tracks and hydraulic systems are well-maintained, ensuring optimal performance.