



**Albatross Equipment Earthworks**  
10998 WY-789 Riverton, WY 82501  
[www.albatrossequipment.com](http://www.albatrossequipment.com)

## Inspection Checklist for 2021 John Deere 325G

### Equipment Details:

**Model:** 2021 John Deere 325G

**Hours:** 260

**Condition:** Good



### Exterior Condition

- - Loader arms show no signs of bending, cracking, or excessive wear.
- - Paint is intact with only minor cosmetic wear from normal use.
- - No visible rust or corrosion on the chassis or loader components.

### Hydraulic System

- - Hydraulic fluid levels are within the recommended range.
- - No leaks detected in hydraulic hoses, cylinders, or connections.
- - Hydraulic pumps are operational and free of unusual noises.
- - Auxiliary hydraulic lines and couplers are functional and undamaged.

### Engine

- - Engine starts smoothly with no unusual noises or excessive smoke.
- - Engine oil and coolant levels are at recommended levels.
- - Air filters are clean and unclogged.
- - No visible leaks in engine compartments or fuel lines.

### Undercarriage

- - Tracks exhibit uniform wear with at least 85% tread life remaining.
- - Track tension is properly adjusted.
- - Drive sprockets and rollers are in good condition with minimal wear.

### **Operator Controls & Cabin**

- - All operator controls are functional and responsive.
- - Joysticks, pedals, and switches show no signs of excessive wear.
- - Seat and restraints are intact and free of damage.
- - Cabin interior is clean with no visible damage to panels or glass.
- - Heat and air conditioning systems are operational.

### **Electrical System**

- - All lights, including work lights and indicators, are functional.
- - Instrument panel displays accurate readings.
- - Battery and charging system are in good condition.

### **Attachments**

- - Standard bucket is securely attached with no visible cracks or deformations.
- - Hydraulic quick-attach system operates correctly.
- - Cutting edge on the bucket shows minor wear, within acceptable limits.

### **General Performance**

- - Machine operates smoothly during forward and reverse travel.
- - Loader arms lift and lower without hesitation or drift.
- - Pivot points are greased and free of excessive wear.
- - Braking and parking systems are functional and reliable.

### **Overall Summary:**

The 2021 John Deere 325G skid steer is in good condition with minor cosmetic wear consistent with its 260 operating hours. All systems, including the hydraulic, engine, undercarriage, and electrical, are functioning well. The machine is work-ready and requires no immediate maintenance.