



**Albatross Equipment Earthworks**  
10998 WY-789 Riverton, WY 82501  
[www.albatrossequipment.com](http://www.albatrossequipment.com)

## Inspection Checklist for 2021 Kubota SSV75

- Model Name: 2021 Kubota SSV75
- Machine Hours: 260
- Condition: Good



### Cab and Operator Controls

- Cab Condition: cab is in good condition, with no visible damage or excessive wear.
- Seat Condition: Operator seat is in good condition with no tears or excessive wear.
- Joystick Controls: Controls are responsive and free from sticking or excessive play.

### Hydraulic System

- Hydraulic Hoses: Inspected for leaks, cracks, or wear – no issues detected.
- Auxiliary Hydraulics: System functions as intended; no leaks or performance issues.
- Hydraulic Quick Coupler: Operates smoothly, securely attaching/detaching attachments without difficulty.

### Tracks and Undercarriage

- Rubber Tracks: Tracks are at 100% tread life, exhibiting no signs of cracking, cuts, or uneven wear.
- Undercarriage Components: Components, including rollers and sprockets, are in good condition with no signs of excessive wear.

### Engine and Performance

- Engine Operation: Engine starts smoothly, runs without unusual noise, smoke, or vibration.
- Oil Levels: Checked and at appropriate levels; no leaks detected.

- Coolant Levels: Within recommended range, with no signs of contamination or leaks.
- Exhaust System: Free of visible damage or obstructions.

### **Electrical System**

- Front Electric System: Functional; no issues detected with connections or operation.
- Lighting: All lights are operational and free of damage.
- Battery: Terminals are clean, secure, and free from corrosion. Voltage within acceptable range.

### **Bucket and Loader Arms**

- Bucket Condition: General-purpose Bobcat bucket is in good condition, with no dents, cracks, or excessive wear.
- Loader Arms: Inspected for cracks, bends, or welds – none found. Movement is smooth and controlled.

### **Operational Test**

- Two-Speed Function: Verified; shifts between speeds seamlessly.
- Steering: Steering is responsive and smooth.
- Brakes: Functional, with no unusual noises or reduced effectiveness.
- Driving Test: Machine runs and operates very well; no operational issues noted.

### **Exterior Condition**

- Paint and Body Panels: Good condition, with minor scratches consistent with normal use.
- Glass and Mirrors: Free from cracks, chips, or impairments.

### **Overall Assessment:**

The 2021 Kubota SSV75 is in good condition, with minimal signs of wear given its 260 hours of operation. All major systems are operational, and the machine performs well during testing. Rubber tracks and undercarriage components are at 100% condition, and the general-purpose bucket is in excellent shape. This unit is work-ready and requires no immediate repairs or maintenance.