



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2021 Kubota SVL65-2

- **Model:** Kubota SVL65-2
- **Year:** 2021
- **Machine Hours:** 377
- **Condition:** Good



General Appearance

- **Exterior Condition:**
 - Paint shows minor wear, typical for 377 hours of use—no rust or significant scratches.
 - Decals intact and legible.
 - Panels properly aligned and secured—no visible dents or structural damage.
 - **Cabin Condition:**
 - Cabin interior clean and free from debris.
 - Operator seat in good condition—no tears or excessive wear.
 - All glass intact—no cracks or visibility issues.
-

Engine and Powertrain

- **Engine Performance:**
 - Engine starts easily and operates smoothly.
 - No unusual noises or vibrations detected during operation.
 - Exhaust emissions clear—no excessive smoke observed.
 - **Engine Components:**
 - Belts and hoses show no cracks or fraying.
 - Fluid levels (oil, coolant) within recommended range—no leaks detected.
-

Hydraulic System

- **Hydraulic Hoses and Lines:**
 - Inspected for wear, cracks, and leaks—none found.
 - Fittings secure and free of corrosion.
 - **Hydraulic Fluid:**
 - Fluid level sufficient and free of contamination.
 - **Performance:**
 - Hydraulic functions responsive, including auxiliary hydraulics.
-

Tracks and Undercarriage

- **Track Condition:**
 - 16" rubber tracks show 85% tread remaining—minimal wear.
 - No visible cuts, cracks, or damage to track surface.
 - **Rollers and Idlers:**
 - Inspected for wear—no excessive play or damage noted.
 - Tracks aligned correctly with no derailment during operation.
-

Loader and Attachments

- **Loader Arms:**
 - Inspected for bending, cracks, or excessive wear—no issues detected.
 - All pivot points lubricated and operational.
 - **Bucket Condition:**
 - 68" GP bucket shows minor wear on cutting edge—no cracks or deformations.
 - Hydraulic SSL Quick Attach operates as designed, securely holding bucket.
-

Electrical System

- **Controls and Displays:**
 - Pilot controls smooth and responsive.
 - Instrument panel fully functional—no error codes displayed.
 - **Lights and Electrical Features:**
 - Headlights, safety lights, and cabin lights operational.
 - Radio and HVAC system functional.
-

Operational Performance

- **Driving Performance:**
 - Tracks provide smooth, stable movement across various terrains.
 - 2-speed travel system operational—transition between speeds smooth.
 - **Lift and Tilt Functions:**
 - Lift and tilt capacities tested—no hesitation or performance issues noted.
-

Overall Condition

- Equipment rated in **Good Condition** for its age and hours.
 - Minor wear consistent with normal use—ready for immediate work.
-

Conclusion

The 2021 Kubota SVL65-2 has been professionally inspected and verified to be in **Good Condition**, with no major repairs needed. All systems are operational and meet manufacturer specifications. This skidsteer is well-maintained and ready for work.