



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2021 Kubota SVL95-2S

- **Model:** Kubota SVL95-2S
- **Year:** 2021
- **Machine Hours:** 596
- **Condition:** Good



1. Exterior Condition

- **Loader Arms:** No signs of bending, cracks, or excessive wear.
- **Paint and Body Panels:** Minor scratches; no major dents or rust.
- **Cab Enclosure:** Glass intact; seals in excellent condition.

2. Hydraulic System

- **Hydraulic Hoses:** Inspected for leaks and wear—no issues found.
- **Hydraulic Fluid Levels:** Checked; within recommended range.
- **Auxiliary Hydraulics:** High flow system tested and functioning properly.

3. Engine and Cooling System

- **Engine Performance:** Smooth operation; no unusual noises or vibrations.
- **Coolant Levels and Radiator:** Checked; coolant levels adequate; radiator clean.
- **Air Filter:** Inspected and in good condition.

4. Tracks and Undercarriage

- **Rubber Tracks:** 85% tread life remaining; uniform wear with no damage.
- **Undercarriage Components:** No excessive wear or damage detected.

- **Track Tension:** Properly adjusted.

5. Operator Cabin and Controls

- **Controls:** Responsive; all buttons, switches, and pilot controls functional.
- **Heating and Air Conditioning:** Fully operational; provides appropriate temperature control.
- **Radio:** Verified and working properly.

6. Bucket and Quick Attach

- **Bucket Condition:** 78" GP bucket in good condition with minimal wear.
- **Hydraulic SSL Quick Attach:** Operates smoothly; no leaks or malfunctions.

7. Electrical System

- **Lights and Indicators:** All lights and warning indicators functional.
- **Battery:** Tested; holds charge and connections are secure.

8. Fluids and Filters

- **Engine Oil:** Recently changed; no contaminants detected.
- **Fuel System:** Free of leaks; diesel fuel quality checked.
- **Hydraulic Oil:** Clean and at recommended levels.

9. Performance Testing

- **Lifting Capacity:** Verified at 3,198 lbs; meets specifications.
- **Travel Speed:** 2-speed travel operates as expected.
- **Steering and Maneuverability:** Smooth and precise during operation.

Inspection Summary

The **2021 Kubota SVL95-2S** is in **good condition**, with minor cosmetic wear and no significant mechanical or hydraulic issues. All systems are fully operational, and the machine is work-ready. With 596 hours of operation, this Skidsteer is well-maintained and reliable for heavy-duty use.