



Albatross Equipment Earthworks
10998 WY-789 Riverton, WY 82501
www.albatrossequipment.com

Inspection Checklist for 2021 Caterpillar 262D3

Equipment: 2021 Caterpillar 262D3
Condition: Good
Machine Hours: 2,624



Operator's Cabin (EROPS)

- **Structural Integrity:** Cabin structure inspected; no visible damage, dents, or deformations.
- **Glass:** Windows and doors free of cracks or chips; fully functional seals.
- **Interior Controls:** Operator controls are responsive with no signs of wear or stickiness.
- **Seat Condition:** Seat padding and adjustments intact; no tears or excessive wear.
- **Climate Control:** Heating and air conditioning systems fully operational.
- **Dashboard Display:** All indicators, gauges, and warning lights are functional.
- **Electrical Systems:** Lights, horn, and switches tested and in good working condition.

Hydraulic System

- **Hydraulic Hoses and Lines:** Inspected for leaks, cracks, or abrasions; no issues found.
- **Auxiliary Valves:** Fully functional and free of blockages.
- **Hydraulic Pump and Flow:** High Flow XPS system tested and performing within specifications.
- **Fluid Levels:** Hydraulic fluid at recommended level; no contamination or discoloration detected.

Engine

- **Startup:** Smooth start with no delays or unusual noises.
- **Performance:** Engine operates at consistent RPM with no vibrations.
- **Exhaust:** Emissions clean; no excessive smoke.

- **Fluid Levels:** Oil, coolant, and other fluids checked and topped off as needed.
- **Belts and Hoses:** No visible wear, cracks, or fraying.

Loader Arms and Bucket

- **Loader Arms:** Inspected for cracks, bending, or excessive wear; none observed.
- **Pins and Bushings:** Proper lubrication; no play or unusual wear noted.
- **Quick Attach System:** Hydraulic quick attach system operates smoothly; locks securely.
- **Bucket Condition:** Bucket shows minor wear consistent with hours; cutting edge intact.

Tires and Undercarriage

- **Tire Condition:** Tires exhibit 75% tread life; no cuts, bulges, or uneven wear.
- **Pressure:** Verified within manufacturer's specifications.
- **Wheel Bearings:** No excessive play or unusual noises detected.

Drivetrain

- **2-Speed Transmission:** Shifts smoothly between speeds; no delays or jerking.
- **Brakes:** Effective stopping power with no unusual noises.
- **Steering:** Tested and functions without excessive resistance or drift.

Electrical Components

- **Battery:** Battery terminals clean and secure; charge holding steady.
- **Wiring:** Inspected for fraying or damage; all connections secure.

General Observations

- **Overall Condition:** Equipment is in good operational condition with minor cosmetic wear.
- **Maintenance History:** Recently serviced; fluids topped off and filters replaced.

Conclusion

This 2021 Caterpillar 262D3 Skidsteer Loader is in **good condition**, fully operational, and work-ready. Minor wear is consistent with machine hours and does not impact functionality. All critical systems, including hydraulics, drivetrain, and engine, are performing within manufacturer's specifications.